

**HISTORIC RESOURCES SURVEY UPDATE
TECHNICAL MEMORANDUM**

**I-75 (SR 93A) FROM MOCCASIN WALLOW ROAD
TO SOUTH OF US 301
HILLSBOROUGH AND MANATEE COUNTIES, FLORIDA**

Work Program Item Segment No.: 419235-2-22-01

Prepared for:



**Florida Department of Transportation
District Seven
11201 North McKinley Drive
Tampa, Florida 33612-6456**

The environmental review, consultation, and other actions required by applicable federal environmental laws for this project are being, or have been, carried out by FDOT pursuant to 23 U.S.C. § 327 and a Memorandum of Understanding December 14, 2016 and executed by FHWA and FDOT.

May 2020

**HISTORIC RESOURCES SURVEY UPDATE
TECHNICAL MEMORANDUM**

**I-75 (SR 93A) FROM MOCCASIN WALLOW ROAD
TO SOUTH OF US 301
HILLSBOROUGH AND MANATEE COUNTIES, FLORIDA**

Work Program Item Segment No.: 419235-2-22-01

Prepared for:



**Florida Department of Transportation
District Seven
11201 North McKinley Drive
Tampa, Florida 33612-6456**

Prepared by:

**Archaeological Consultants, Inc.
8110 Blaikie Court, Suite A
Sarasota, Florida 34240**

In association with:

**American Consulting Professionals, LLC
2818 Cypress Ridge Boulevard, Suite 200
Wesley Chapel, FL 33544**

May 2020

TABLE OF CONTENTS

1. INTRODUCTION.....	1
2. BACKGROUND RESEARCH.....	3
3. SURVEY METHODOLOGY.....	6
4. SURVEY RESULTS.....	6
5. CONCLUSIONS.....	15
6. BIBLIOGRAPHY	16

APPENDICES

- Appendix A: SHPO Correspondence
- Appendix B: FMSF Forms
- Appendix C: Demolished Building Letter
- Appendix D: Survey Log

LIST OF FIGURES

Figure 1. Location of the I-75 (SR 93A) study area, Manatee and Hillsborough Counties.	2
Figure 2. 1957 and 1995 aerial photographs showing development of the I-75 (SR 93A) corridor between Big Bend Road and Progress Boulevard/Bloomingdale Avenue.....	5
Figure 3. Location newly recorded (red text box) and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	7
Figure 4. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	8
Figure 5. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	9

LIST OF TABLES

Table 1. Previously recorded historic resources during the 2009 survey and the 2020 survey of Big Bend Road (CR 672).	4
Table 2. Newly identified historic resources within the APE.....	6

LIST OF PHOTOS

Photo 1. 1515 SE 30 th Street (8HI14678), looking west-southwest.....	10
Photo 2. 12113 East Bay Road (8HI14679), looking west.	11
Photo 3. 12039 East Bay Road (8HI14680), looking west.	12
Photo 4. 9709 Riverview Drive (8HI14681), looking south.	13
Photo 5. 9708 Lorrayne Road (8HI14682), looking east.	14
Photo 6. 8012 Formby Street (8HI14683), looking northeast.....	15

1. INTRODUCTION

Archaeological Consultants, Inc. (ACI) performed a Historic Resources Survey Update (HRSU) of Interstate 75 (I-75) (State Road [SR] 93A) from Moccasin Wallow Road in Manatee County to south of US 301 (SR 43) in Hillsborough County, Florida (**Figure 1**). This historic resources survey updates the previous Project Development and Environment (PD&E) Cultural Resource Assessment Survey (CRAS) with resources that were not historic at the time of preparation by ACI in 2009 (ACI 2009). The previous CRAS report prepared for the PD&E Study in 2009 was reviewed and concurred with by the State Historic Preservation Officer (SHPO) on January 19, 2010 (ACI 2009; Kammerer 2010; **Appendix A**). The historic area of potential effects (APE) extends 300-feet (ft) from the edge of existing right-of-way (ROW), and a maximum of 3000 feet of the centerline of I-75 along Gibsonton Drive, CR 672 (Big Bend Road), and SR 674 (Sun City Center Boulevard/E. College Avenue). This APE remains in-keeping with the 2009 CRAS. The historical/architectural field survey was conducted in October 2019. This is a federally-funded project.

The purpose of the 2020 HRSU is to locate, identify, and evaluate any resources which have become historic (50 years of age or older) since the previous CRAS (ACI 2009) within the APE and to assess their significance in terms of eligibility for listing in the National Register of Historic Places (NRHP). All work was conducted to comply with Section 106 of the *National Historic Preservation Act* of 1966, as amended by Public Law 89-665; the *Archaeological and Historic Preservation Act*, as amended by Public Law 93-291; Executive Order 11593; and Chapter 267, *Florida Statutes (FS)*. All work was carried out in conformity with Part 2, Chapter 8 (“Archaeological and Historical Resources”) of the FDOT’s *Project Development and Environment (PD&E) Manual* (Florida Department of Transportation [FDOT] 2019), and the Florida Division of Historical Resources’ (FDHR) standards contained in the *Cultural Resource Management Standards and Operational Manual* (FDHR 2003), as well as with the provisions contained in the Chapter 1A-46, *Florida Administrative Code (FAC)*. Principal Investigators meet the *Secretary of the Interior’s Historic Preservation Professional Qualification Standards* (48 FR 44716) for archaeology, history, architecture, architectural history, or historic architecture.

The FDOT District Seven, is proposing roadway improvements to a segment of I-75 (SR 93A) from Moccasin Wallow Road in Manatee County to south of US 301 (SR 43) in Hillsborough County, Florida. The proposed project will widen the existing roadway from a six-lane section to an ten-lane section. The existing I-75 roadway includes three (3) 12-ft travel lanes, a 12-ft inside shoulder (10 ft paved), and a 12-ft wide outside shoulder (10-ft paved) with a depressed grass median and roadside ditches. The median width varies from approximately 85-ft to 184-ft. The existing ROW width varies from approximately 348-ft to 447-ft and to 1,193-ft.

A review of relevant historic United States Geographical Survey (USGS) quadrangle maps, historic aerial photographs, and the Manatee and Hillsborough County Property Appraiser’s data revealed the potential for six new historic resources 50 years of age or older (constructed in 1969 or earlier) within the APE (Hackney 2019; Henriquez 2019). The historic/architectural field survey resulted in the identification and evaluation of six new historic resources (8HI14678-8HI14683). These include four Frame Vernacular (8HI14678; 8HI14681-8HI14683) and two Masonry Vernacular (8HI14679 & 8HI14680) style buildings constructed between circa (c.) 1957 and 1969. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appears eligible for listing in the NRHP, either individually or as part of a historic district. Field survey also revealed that two previously recorded historic resources (8HI11300 & 8HI11301) are no longer extant.




Figure 1. Location of the I-75 (SR 93A) study area, Manatee and Hillsborough Counties.

2. BACKGROUND RESEARCH

Field survey was preceded by background research, which included a check of the digital database of the Florida Master Site File (FMSF) in October 2019, and the NRHP, as well as examination of previous studies along and adjacent to the I-75 corridor segment from Moccasin Wallow Road to south of US 301. In-depth historic and prehistoric overviews were included in the PD&E CRAS and are not repeated here. The following is an updated project specific historic context.

The construction of I-75 was authorized by the Federal Highway Act of 1956. The original plan, stretching 212 miles from the Florida-Georgia border south to Tampa, was constructed between 1963 and 1968. During construction, communities in southwest Florida lobbied to have I-75 continue farther south and as a result, the Tampa to Naples Extension was constructed between 1979 and 1986. The final segment of I-75 was completed with the conversion of Alligator Alley into a portion of the Interstate System. With completion of the route across Alligator Alley, I-75 now connects Sault Ste. Marie, Michigan to Miami, Florida (AARoads 2020). Throughout the last fifty years, commercial development, including tourist attractions such as Busch Gardens, restaurants, and hotels, have exploded along the interstate system, keeping tourism as a primary revenue source in Florida.

Within the APE, the southern portion of the corridor remains rural in nature, specifically in the area between Moccasin Wallow Road in Manatee County to Sun City Center/E College Avenue in Hillsborough County. The Sun City Center/E College Avenue interchange has not been significantly altered over the past decade; however, the land to the north has become increasingly more developed. With the development of I-75 and new interchanges also came new roads such as Big Bend Road and Gibsonton Drive (**Figure 2**). Interchanges including those at Big Bend Road and Gibsonton Road have experienced significant growth over the last decade with the construction of new apartment complexes, convenience stores, retail spaces, a movie theater, and a local community center (YMCA).

The previous CRAS conducted by ACI in 2009, *A Cultural Resource Assessment Survey Project Development and Environment Study from Moccasin Wallow Road to South of US 301 Manatee and Hillsborough Counties*, as well as the *Preliminary Technical Memorandum for Proposed Stormwater Management Facilities from Moccasin Wallow Road to south of US 301* were reviewed (ACI 2009; Survey No. 18022; ACI 2019a). The historic results of the previous CRAS identified eight new historic buildings constructed between c. 1945 and 1960, all of which were determined ineligible for listing in the NRHP (**Table 1**). The PD&E document was submitted to and approved by the SHPO in 2010 (Kammerer 2010). Of these, six resources are associated with possible interchange modification areas along Old Big Bend Road (8HI11296-8HI11297) and Gibsonton Drive (8HI11298-8HI11301).

In addition, in March 2020, ACI prepared the *CRAS PD&E Study Big Bend Road (CR 672) from west of Covington Gardens Drive to east of Simmons Loop, Hillsborough County, Florida* as part of proposed roadway improvements at Big Bend Road (CR 672) (ACI 2020). As a result of the CRAS, five historic resources (8HI12163, 8HI12164, 8HI12165, 8HI12166, and 8HI14910) were newly identified, recorded, and evaluated. These include a ca. 1954 concrete slab bridge over Bullfrog Creek (FDOT Bridge No. 100271; 8HI12163); one Masonry Vernacular style building (8HI12166); two Industrial Vernacular style buildings (8HI12164, 8HI12165) constructed between ca. 1961 and ca. 1969; and one linear resource, Old Big Bend Road (8HI14910) constructed in ca. 1938. The Bullfrog Creek Bridge is a common slab type bridge that lacks engineering, architectural, and historical distinction. Overall, the buildings and linear resource have been altered, lack sufficient architectural or engineering features, and are not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant

persons and/or events. Therefore, the resources did not appear eligible for listing in the NRHP, either individually or as a part of a historic district. None of these resources have been evaluated by the SHPO.

Table 1. Previously recorded historic resources during the 2009 survey (Survey No. 18022) and the 2020 survey of Big Bend Road (CR 672).

FMSF	Address	Style/Type	Build Date	NRHP Evaluation
8HI11295	2201 18 th Avenue SE	Frame Vernacular	1945	Ineligible
8HI11296	6908 Simmons Loop Road	Ranch	1955	Ineligible
8HI11297	9922 Old Big Bend Road	Frame Vernacular	1950	Ineligible
8HI11298	9002 Gibsonton Drive	Masonry Vernacular	1955	Ineligible
8HI11299	9208 Gibsonton Drive	Ranch	1955	Ineligible
8HI11300	9212 Gibsonton Drive	Masonry Vernacular	1955	Ineligible
8HI11301	10010 Gibsonton Drive	Masonry Vernacular	1960	Ineligible
8HI11302	8007 Formby Street	Masonry Vernacular	1960	Ineligible
8HI12163	Bullfrog Creek (FDOT Bridge No. 100271)	Bridge	1954	Appears ineligible
8HI12164	8718-C Old Big Bend Rd	Industrial Vernacular	1966	Appears ineligible
8HI12165	8718-D Old Big Bend Rd	Industrial Vernacular	1961	Appears ineligible
8HI12166	8850 Old Big Bend Rd	Masonry Vernacular	1969	Appears ineligible
8HI14910	Old Big Bend Road	Linear Resource	1938	Appears ineligible

*Purple highlight denotes historic resources recorded during the recent 2020 Big Bend Road PD & E survey and have not been evaluated by the SHPO.

A review of relevant historic United States Geographical Survey (USGS) quadrangle maps (Brandon 1956a, Gibsonton 1956b, Riverview 1956c, Ruskin 1956d, Palmetto 1964, Parrish 1973), historic aerial photographs, and the Manatee and Hillsborough County Property Appraiser’s data revealed the potential for six new historic resources 50 years of age or older (constructed in or prior to 1969) within the APE (Hackney 2019; Henriquez 2019).




Figure 2. 1957 and 1995 aerial photographs showing development of the I-75 (SR 93A) corridor between Big Bend Road and Progress Boulevard/Bloomington Avenue.

3. SURVEY METHODOLOGY

Historic/architectural field methodology consisted of a field survey of the APE to determine and verify the location of all buildings and other historic resources (i.e. bridges, roads, cemeteries) that are 50 years of age or older (built in or prior to 1969), and to establish if any such resources could be determined eligible for listing in the NRHP. The field survey focused on the assessment of existing conditions for all previously recorded historic resources located within the APE, and the presence of unrecorded historic resources within the project area. For each property, photographs were taken, and information needed for the completion of FMSF forms was gathered. In addition to architectural descriptions, each historic resource was reviewed to assess style, historic context, condition, and potential NRHP eligibility. Also, informant interviews would have been conducted, if possible, with knowledgeable persons to obtain site-specific building construction dates and/or possible associations with individuals or events significant to local or regional history.

4. SURVEY RESULTS

As a result of historic field survey, six historic resources (8HI14678-HI14683) were identified, recorded, and evaluated within APE (**Table 2; Figures 3-5**). These include four Frame Vernacular (8HI14678; 8HI14681-8HI14683) and two Masonry Vernacular (8HI14679 & 8HI14680) style buildings constructed between circa (c.) 1957 and 1969. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appears eligible for listing in the NRHP, either individually or as part of a historic district. Descriptions of the resources follow, and FMSF forms are contained in **Appendix B**. Field survey also revealed that two previously recorded historic resources (8HI11300 & 8HI11301) are no longer extant. A letter to the FMSF noting their changed status is contained in **Appendix C**.

Table 2. Newly identified historic resources within the APE.

FMSF No.	Address/Site Name	Build Date	Style/Type	NRHP Eligibility Recommendation
8HI14678	1515 SE 30th Street	c. 1960	Frame Vernacular	Ineligible
8HI14679	12113 East Bay Road	c. 1966	Masonry Vernacular	Ineligible
8HI14680	12039 East Bay Road	c. 1966	Masonry Vernacular	Ineligible
8HI14681	9709 Riverview Drive	c. 1969	Frame Vernacular	Ineligible
8HI14682	9708 Lorraine Road	c. 1957	Frame Vernacular	Ineligible
8HI14683	8012 Formby Street	c. 1964	Frame Vernacular	Ineligible




Figure 3. Location newly recorded (red text box) and previously recorded (black text box) historic resources within the I-75 (SR 93A) corridor APE.




Figure 4. Location newly recorded (red text box) and previously recorded (black text box) historic resources within the I-75 (SR 93A) corridor APE.




Figure 5. Location newly recorded (red text box) and previously recorded (black text box) historic resources within the I-75 (SR 93A) corridor APE.



Photo 1. 1515 SE 30th Street (8HI14678), looking west-southwest.

8HI14678: The Frame Vernacular style building at 1515 SE 30th Street was constructed in c. 1960 per property appraiser's data; however, the building appears to have been constructed at an earlier date (**Photo 1**). A review of historic aerial photography revealed that the building was moved to the property between c. 1980 and c. 1984 (FDOT 1980, 1984). The one-story, irregular plan building rests on a pre-cast tapered concrete pier foundation and has a wood-frame structural system clad in asbestos siding. The front gable roof and gable extension are covered with 3v crimp sheet metal, while the half hip pent roof is covered in composition shingles. A brick chimney is located on the ridge of the main roof. The main entryway is on the east elevation within a partial width open porch beneath a gable extension with screening, half walls, and wooden brackets. Visible windows include individual and paired, one-over-one wood single-hung-sash units. Distinguishing architectural features include overhanging eaves, wooden window casings, gable vent, wooden brackets, brick chimney, tapered concrete piers, and corner boards. Alterations include replacement roofing, windows, and siding. A non-historic utility shed is located to the northwest. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14678 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 2. 12113 East Bay Road (8HI14679), looking west.

8HI14679: The Masonry Vernacular style building at 12113 East Bay Road was constructed in c. 1966 (**Photo 2**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in brick veneer, stucco, and clapboard siding. The cross-gabled roof with side gable extension are covered in composition shingles, while the flat roof is covered in composition roll. The main entryway is on the east elevation through a single door within a partial width open porch beneath a flat roof supported by metal porch supports. Visible windows include a mixture of individual, one-over-one and eight-over-eight metal single-hung-sash units. Distinguishing architectural features include clapboard siding in the gable ends, brick windowsills, and boxed rafters. Alterations include replacement roofing and siding. Additions include an attached garage on the south elevation, a flat roof porch on the east elevation, and two additions to the west elevation. A non-historic detached garage, detached carport, and utility shed are located to the south of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14679 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 3. 12039 East Bay Road (8HI14680), looking west.

8HI14680: The Masonry Vernacular style building at 12039 East Bay Road was constructed in c. 1966 (**Photo 3**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system partially clad in brick veneer and clapboard siding. The side gable roof with gable extension are covered in composition shingles. The main entryway is on the east elevation through a single door with two rectangular leaded lights within a partial width open porch beneath a gable extension supported by column porch supports. Visible windows include a mixture of individual and paired, eight-over-eight vinyl single-hung-sash units and individual, two-over-two vinyl single-hung-sash units. Distinguishing architectural features include clapboard siding in the gable ends, boxed rafters, canvas awnings, and column porch supports. The property is surrounded by metal fence with four square masonry piers with lion caps at the front entrance. Alterations include replacement roofing and windows. A non-historic detached garage and swimming pool with screened enclosure are located to the west of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14680 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 4. 9709 Riverview Drive (8HI14681), looking south.

8HI14681: The Frame Vernacular style building at 9709 Riverview Drive was constructed in c. 1969 (**Photo 4**). The one-story, irregular plan building rests on a concrete slab foundation and has a wood-frame structural system clad in plywood. The side gable roof and shed roof are covered with composition shingles, while the flat roof is sheathed in built up membrane. The main entryway is on the northeast elevation through a single panel door with fanlight within a partial-width open porch beneath the shed roof overhang. An open, partial-width porch beneath a flat roof with vinyl porch supports is located on the southwest elevation. Visible windows include a mixture of individual and paired, one-over-one and three-over-three vinyl single-hung-sash units and paired, six-over-six vinyl single-hung-sash units. Distinguishing architectural features include wide base molding, wood window frames and door surrounds, and overhanging eaves. Alterations include replacement roofing, siding, and windows. An addition is located on the south elevation beneath a shed roof and two porches on the southwest elevation beneath a flat roof. A non-historic detached garage is located immediately adjacent to the east of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14681 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 5. 9708 Lorraine Road (8HI14682), looking east.

8HI14682: The Frame Vernacular style building at 9708 Lorraine Road was constructed in c. 1957 (**Photo 5**). The one-story, irregular plan building rests on a concrete slab foundation and has a wood-frame structural system clad in vinyl siding. The side gable roof and gable extension are covered with composition shingles, while the shed extension is covered with 3v crimp sheet metal. The main entryway is on the west elevation through a single panel door with a rectangular light. Preceding the entryway is a partial width open porch beneath a gable extension supported by wooden porch supports with railings accessed by two wooden steps with a wooden railing. Visible windows include a mixture of individual, one-over-one, two-over-one, two-over-two, and one-over-four vinyl single-hung-sash units. Distinguishing architectural features include faux knee braces, decorative trim in the gable ends, and wood window frames. Alterations include replacement roofing, siding, and windows. Additions include gable roof extensions on the south and west elevation completed during a c. 2018 renovation and a carport on the north elevation. A non-historic utility shed is located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14682 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 6. 8012 Formby Street (8HI14683), looking northeast.

8HI14683: The Frame Vernacular style building at 8012 Formby Street was constructed in c. 1964 (**Photo 6**). The one-story, irregular plan building rests on a concrete slab foundation and has a wood-frame structural system clad in stucco. The side gable roof is covered with composition shingles, while the shed roof is covered with 5V crimp sheet metal. The main entryway is on the west elevation through within a partial-width open screened-in porch beneath a shed roof supported by metal porch supports. Visible windows include a mixture of individual, one-over-one and eight-over-eight vinyl single-hung-sash units. Distinguishing architectural features include contrasting trim with keystones around windows and overhanging eaves. Alterations include replacement roofing, siding, and windows. Additions include porch with shed roof on the west and east elevations. A non-historic detached carport is located to the west of the building and a non-historic utility shed is located to the north. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14683 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.

5. CONCLUSIONS

Background research indicated 13 historic resources were previously recorded within the I-75 APE. No significant alterations have occurred to 13 previously evaluated resources since they were recorded; therefore, an updated FMSF form was not prepared. As a result of the I-75 (SR 93A) HRSU six historic resources (8HI14678-8HI14683) were newly identified, recorded, and evaluated. These include four Frame Vernacular (8HI14678; 8HI14681-8HI14683) and two Masonry Vernacular (8HI14679 & 8HI14680) style buildings constructed between circa (c.) 1957 and 1969. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appears eligible for listing in the NRHP, either individually or as part of a historic district. Field survey also revealed that two previously recorded historic resources (8HI11300 & 8HI11301) are no longer extant. The FMSF forms for the newly recorded resources are contained in **Appendix B** and a letter to the FMSF noting the changed status of the previously recorded buildings is contained in **Appendix C**.

6. BIBLIOGRAPHY

AA Roads

- 2020 State Road 618 – Lee Roy Selmon Expressway. <https://www.aaroads.com/guides/fl-618/> (accessed April 16, 2020).

Archaeological Consultants, Inc. (ACI)

- 2009 Cultural Resource Assessment Survey Interstate 75 (I-75) Project Development and Environment (PD&E) Study I-75 from Moccasin Wallow Road to South of US 310, Manatee and Hillsborough Counties, Florida. ACI, Sarasota.
- 2019a Preliminary Cultural Resource Assessment Probability Analysis Technical Memorandum Proposed SMF and FPC Sites I-75 from Moccasin Wallow Road to South of US 301, Manatee and Hillsborough Counties, Florida. ACI, Sarasota.
- 2020 Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study Big Bend Road (CR 672) from west of Covington Gardens Drive to east of Simmons Loop and the I-75 at Big Bend Road Interchange, Hillsborough County, Florida. ACI, Sarasota.

Florida Department of Transportation (FDOT)

- 1980 Aerial Photograph. 10-13-80, PD2687-8-04. APLUS, Tallahassee.
- 1984 Aerial Photograph. 4-24-84, PD3112-8-05. APLUS, Tallahassee.
- 2019 *Project Development and Environment Manual, Part 2, Chapter 8, Archaeological and Historical Resources*. FDOT, Tallahassee.

Florida Division of Historical Resources (DHR)

- n.d. Florida Master Site File Form Information.
- 2003 *Cultural Resource Management Standards and Operational Manual*. FDHR, Tallahassee.

Kammerer, Laura

- 2010 SHPO Concurrence Letter, DHR Project File No.: 2009-7635, Cultural Resource Assessment Survey Interstate 75 (I-75) Project Development and Environment (PD&E) Study I-75 from Moccasin Wallow Road to South of US 310, Manatee and Hillsborough Counties, Florida. ACI, Sarasota.

United States Geological Survey (USGS)

- 1956a Brandon, Fl (Photo Revised, 1987)
- 1956b Gibsonton, Fl (Photo Revised, 1981)
- 1956c Riverview, Fl (Photo Revised, 1987)
- 1956d Ruskin, Fl (Photo Revised, 1987)
- 1964 Palmetto, Fl
- 1973 Parrish, Fl

APPENDIX A: SHPO Correspondence



FLORIDA DEPARTMENT OF STATE
Kurt S. Browning
Secretary of State
DIVISION OF HISTORICAL RESOURCES

Linda Anderson
Federal Highway Department
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

January 19, 2010

RE: DHR Project File No.: 2009-7635 and 2009-7642
WPI Segment No.: 419235-2 and 419235-3
Project: *I-75 from Moccasin Wallow Road to South of US 301 PD&E Study and
I-75 South of US 301 to North Fletcher Avenue PD&E Study*
County: Manatee and Hillsborough

Dear Ms. Anderson:

This office received and reviewed the above referenced project in accordance with Section 106 of the National Historic Preservation Act of 1966 as amended, 36 CFR Part 800: Protection of Historic Properties, and Chapter 267, Florida Statutes. It is the responsibility of the State Historic Preservation Officer to advise and assist, as appropriate, Federal and State agencies in carrying out their historic preservation responsibilities; to cooperate with agencies to ensure that historic properties are taken into consideration at all levels of planning and development; and to consult with the appropriate agencies in accordance with the National Historic Preservation Act of 1966 as amended, on undertakings that may affect historic properties.

The current submittal includes two Project and Development and Environmental (*PD&E*) studies for the portion of I-75 that extends from Moccasin Wallow Road to US 301 (WPI Segment No.: 419235-2) and from US 301 to North Fletcher Avenue (WPI Segment No.: 419235-3). The project includes the widening of I-75 in both directions within the above-stated limits in addition to the modification of existing interchanges.

Background research for the portion of the project that extends along I-75 between Moccasin Wallow Road and US 301 (WPI Segment No.: 419235-2) noted that there were 10 previously-identified archaeological sites (8HI409, 8HI478, 8HI479, 8HI480, 8HI524, 8HI525, 8HI526, 8HI527, 8HI532, and 8MA136) one previously-identified historic structure (8HI11302), and one previously-identified resource group (8MA1337) within the project's area of potential effects (APE). One of the previously-identified archaeological sites, 8HI480, was determined to be eligible for listing in the National Register of Historic Places (NRHP) by this office in 1979, while the remaining nine archaeological sites have yet to be evaluated by the SHPO. The previously-recorded resource group and historic structure were determined to be ineligible for the NRHP by

500 S. Bronough Street • Tallahassee, FL 32399-0250 • <http://www.flheritage.com>

Director's Office
850.245.6300 • FAX: 245.6436

Archaeological Research
850.245.6444 • FAX: 245.6452

Historic Preservation
850.245.6333 • FAX: 245.6437

this office. As a result of the field survey, evidence of only three of the previously-recorded archaeological sites (8HI478, 8HI524, and 8HI532) was located within the project's APE. The field survey also determined that 8HI11302, the previously-identified historic structure within the APE, was no longer extant. Newly-identified resources documented within the APE as a result of the fieldwork included eight buildings (8HI11295-8HI11302), one archaeological site (8HI11359), and two archaeological occurrences (AOs). The report concluded that none of the historic-age architectural resources within the APE were eligible for listing in the NRHP because each lacked architectural and historic import. Similarly, the portion of the three previously-recorded archaeological sites within the APE (8HI478, 8HI524, and 8HI532), the newly-recorded archaeological site 8HI11359, and the two AO's were evaluated and considered to be insignificant and thus ineligible for inclusion in the NRHP. A table in the report noted that the portions of archaeological sites 8HI409, 8HI479, 8HI480, 8HI525, 8HI526, 8HI527, and 8MA136 were ineligible for listing in the NRHP because no evidence of these previously-identified sites was found during the field study.

Background research for the portion of the project that extends along I-75 between US 301 and North Fletcher Avenue (WPI Segment No.: 419235-3) noted that there were 28 previously-identified archaeological sites and eight previously-identified historic structures within the project APE. Of the 36 previously-identified cultural resources, twelve (archaeological sites numbers 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479) were determined to be eligible for listing in the NRHP by this office. As a result of the field survey, evidence of only ten of the 28 previously-recorded archaeological sites (8HI99, 8HI472, 8HI476A, 8HI476B, 8HI507, 8HI510, and 8HI5431, 8HI5432, 8HI5434, and 8HI5926) and all of the eight previously-recorded historic structures were located within the project's APE and reevaluated. Newly-identified resources documented within the APE as a result of the fieldwork include 15 buildings and two resource groups (8HI11460-11472 and 8HI11481-11482) as well as two AOs. The report found that only one of the documented historic structures, the *Tanner Residence* (8HI8742), was eligible for listing in the NRHP. The report also concluded that the newly-recorded AOs and the portions of the 10 previously-recorded archaeological sites found within the APE were ineligible for listing in the NRHP. A table in the report noted that the portions of the remaining 18 previously-identified archaeological sites were ineligible for listing in the NRHP because no evidence of these sites was found during the field study.

After a review of the submitted reports, this office concurs with the Florida Department of Transportation's determination that the *Tanner Residence* (8HI8742) is eligible for listing in the NRHP and looks forward to continuing coordination regarding the affects, if any, that the proposed undertaking will have on this historic property.


The reports noted that the Florida Master Site Files indicated the presence of 13 archaeological sites within the project's APE that had been previously determined to be NRHP eligible by this

Ms. Linda Anderson
DHR Project File No.: 2009-7635 and 2009-7642
January 19, 2010
Page 3

office (sites 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI480, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479). After the field study, the reports concluded that the portion of each of these sites within the APE was ineligible because very little or no cultural material was located as a result of subsurface testing. Please note, for the sake of clarification, that this office seldom confers a dual eligibility designation to a single site (i.e., a site is either *eligible* or *not eligible* for the NRHP). This office therefore finds that sites 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI480, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479 should maintain their status as NRHP eligible, but finds that the project will have *no adverse affect* [as per 36 C.F.R. Part 800, § 800.5(b)] on the sites due to the location of the proposed project and the lack of cultural material present within the project's APE.

If there are any questions concerning our comments or recommendations, please contact Jennifer Ross, Architectural Historian, by phone at 850.245.6333, or via electronic mail at jross@dos.state.fl.us.

Sincerely,



Laura A. Kammerer
Deputy State Historic Preservation Officer
For Review and Compliance

PC: Bob Gleason, FDOT District 5, Deland
Roy Jackson, FDOT CEMO, Tallahassee/#5500

APPENDIX B: FMSF Forms



HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14678**
Field Date 10-30-2019
Form Date 10-31-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 1515 SE 30th Street Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 1515 Direction SE Street Name 30th Street Type Street Suffix Direction _____
Address: _____
Cross Streets (nearest / between) _____
USGS 7.5 Map Name RUSKIN USGS Date 1956 Plat or Other Map PB 6 / PG 24
City / Town (within 3 miles) Ruskin In City Limits? yes no unknown County Hillsborough
Township 32S Range 19E Section 15 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-15-32-19-1US-000000-00522.0 Landgrant _____
Subdivision Name RUSKIN COLONY FARMS Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 362509 Northing 30651160
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1960 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1960 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address Unknown
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Ramon, Delia, & Jim Galvan (2004); Joyce Strickland Trust (2003); Joyce Strickland

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Asbestos 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Sheet metal:3V crimp 2. Composition shingles 3. _____
Roof secondary strucs. (dormers etc.) 1. Gable extension 2. _____

Windows (types, materials, etc.)
SHS, wood, single, paired, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
overhanging eaves, wooden window casings, gable vent, wooden brackets, brick chimney, tapered concrete piers, and corner boards

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 1 Chimney Material(s): 1. Brick 2. _____
 Structural System(s): 1. Wood frame 2. _____ 3. _____
 Foundation Type(s): 1. Piers 2. _____
 Foundation Material(s): 1. Pre-cast Concrete Footi 2. _____

Main Entrance (stylistic details)
 E ELEV: obscured, beneath a gable extension within partial-width open porch.

Porch Descriptions (types, locations, roof types, etc.)
 E/ENTRANCE: open, partial width, beneath a gable extension w/ overhanging half hip eaves supported by wooden brackets, half wall, and screening

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource
 A one-story Frame Vernacular style building with overhanging eaves, wooden window casings, a rectangular gable vent, corner boards, and wooden brackets beneath the overhanging eave of the porch.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- FMSF record search (sites/surveys) library research building permits Sanborn maps
- FL State Archives/photo collection city directory occupant/owner interview plat maps
- property appraiser / tax records newspaper files neighbor interview Public Lands Survey (DEP)
- cultural resource survey (CRAS) historic photos interior inspection HABS/HAER record search
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
 Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient information
 Appears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)
 The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)
 1. _____ 3. _____ 5. _____
 2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents
 Document type All materials at one location Maintaining organization Archaeological Consultants Inc
 1) Document description Files, photos, research, documents File or accession #'s P17097
 2) Document type _____ Maintaining organization _____
 Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
 Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
 (address / phone / fax / e-mail)

Required Attachments	<p>① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED</p> <p>② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)</p> <p>③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE</p> <p>When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.</p>
-----------------------------	---



PHOTOGRAPHS






AERIAL MAP





USGS Ruskin
Township 32 South, Range 19 East, Section 15





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14679**
Field Date 10-30-2019
Form Date 11-1-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 12113 East Bay Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 12113 Direction _____ Street Name East Bay Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) East Bay Road & Bliss Road
USGS 7.5 Map Name RIVERVIEW USGS Date 1956 Plat or Other Map _____
City / Town (within 3 miles) Gibsonton In City Limits? yes no unknown County Hillsborough
Township 30S Range 19E Section 36 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-36-30-19-ZZZ-000001-73360.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 366724 Northing 3078300
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1966 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1966 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding
Additions: yes no unknown Date: _____ Nature Garage, E porch, W elev.
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
S.R. & Martha Linne

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Brick 2. Clapboard 3. Stucco
Roof Type(s) 1. Cross-gabled 2. Flat 3.
Roof Material(s) 1. Composition shingles 2. Composition roll 3.
Roof secondary strucs. (dormers etc.) 1. 2.

Windows (types, materials, etc.)
SHS, metal, single, 1/1, 8/8

Distinguishing Architectural Features (exterior or interior ornaments)
Clapboard siding in gable ends, brick windowsills, boxed rafters

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic detached garage, detached carport, and utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____
 Structural System(s): 1. Concrete block 2. _____ 3. _____
 Foundation Type(s): 1. Slab 2. _____
 Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)
 E ELEV: single door, beneath a flat roof supported by metal porch supports

Porch Descriptions (types, locations, roof types, etc.)
 E/ENTRANCE: open, partial width, beneath a flat roof supported by metal porch supports

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource
 A one-story Masonry Vernacular style building with clapboard siding in gable ends, brick windowsills, and boxed rafters. An attached two-car garage is located on the south elevation.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- FMSF record search (sites/surveys) library research building permits Sanborn maps
- FL State Archives/photo collection city directory occupant/owner interview plat maps
- property appraiser / tax records newspaper files neighbor interview Public Lands Survey (DEP)
- cultural resource survey (CRAS) historic photos interior inspection HABS/HAER record search
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
 Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient information
 Appears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)
 The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)
 1. _____ 3. _____ 5. _____
 2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents
 Document type All materials at one location Maintaining organization Archaeological Consultants Inc
 1) Document description Files, photos, research, documents File or accession #'s P17097
 2) Document type _____ Maintaining organization _____
 Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
 Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
 (address / phone / fax / e-mail)

Required Attachments	<p>① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED</p> <p>② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)</p> <p>③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE</p> <p>When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.</p>
-----------------------------	---




PHOTOGRAPHS






AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors, Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community 2017



USGS Riverview
Township 30 South, Range 19 East, Section 36





HISTORICAL STRUCTURE FORM
FLORIDA MASTER SITE FILE
Version 5.0 3/19

Site#8 HI14680
Field Date 10-30-2019
Form Date 11-1-2019
Recorder #

[X] Original
[] Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the Guide to Historical Structure Forms for detailed instructions.

Site Name(s) (address if none) 12039 East Bay Road Multiple Listing (DHR only)
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only)
National Register Category (please check one) [X]building []structure []district []site []object
Ownership: []private-profit []private-nonprofit []private-individual []private-nonspecific []city []county []state []federal []Native American []foreign []unknown

LOCATION & MAPPING

Street Number 12039 Direction Street Name East Bay Street Type Road Suffix Direction
Address:
Cross Streets (nearest / between) East Bay Road & Bliss Road
USGS 7.5 Map Name RIVERVIEW USGS Date 1956 Plat or Other Map
City / Town (within 3 miles) Gibsonton In City Limits? []yes []no [X]unknown County Hillsborough
Township 30S Range 19E Section 36 1/4 section: []NW []SW []SE []NE Irregular-name:
Tax Parcel # U-36-30-19-ZZZ-000001-73180.0 Landgrant
Subdivision Name Block Lot
UTM Coordinates: Zone []16 [X]17 Easting 366720 Northing 3078374
Other Coordinates: X: Y: Coordinate System & Datum
Name of Public Tract (e.g., park)

HISTORY

Construction Year: 1966 []approximately []year listed or earlier [X]year listed or later
Original Use Residence, private From (year): 1966 To (year): CURR
Current Use From (year): To (year):
Other Use From (year): To (year):
Moves: []yes [X]no []unknown Date: Original address
Alterations: [X]yes []no []unknown Date: Nature Roofing, windows
Additions: []yes [X]no []unknown Date: Nature
Architect (last name first): Builder (last name first):
Ownership History (especially original owner, dates, profession, etc.)
Romaine Billings Nation (1975); Reuben James and Romaine Billings Nation

Is the Resource Affected by a Local Preservation Ordinance? []yes []no [X]unknown Describe

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Brick 2. Concrete block 3. Clapboard
Roof Type(s) 1. Gable 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. Gable extension 2.
Windows (types, materials, etc.)
SHS, vinyl, single, paired, 8/8; SHS, vinyl, single, 2/2

Distinguishing Architectural Features (exterior or interior ornaments)
Clapboard siding in gable ends, boxed rafter tails, canvas awnings, column porch supports

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic detached garage and swimming pool with screen enclosure; property is surrounded by metal fence with 4 square masonry piers with lion caps

Table with 3 columns: DHR USE ONLY, OFFICIAL EVALUATION, DHR USE ONLY. Contains fields for NR List Date, Owner Objection, SHPO listing criteria, and NR Criteria for Evaluation.

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Concrete, Generic 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

E ELEV: single door w/ two rectangular leaded lights, beneath a gable extension supported by column porch supports

Porch Descriptions (types, locations, roof types, etc.)

E/ENTRANCE: open, partial width, beneath a front gable extension supported by column porch supports

Condition (overall resource condition): [] excellent [x] good [] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building with clapboard siding in gable ends, boxed rafters, canvas awnings, and column porch supports.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P17097
2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS






AERIAL MAP





USGS Riverview
Township 30 South, Range 19 East, Section 36





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14681**
Field Date 10-30-2019
Form Date 10-31-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9709 Riverview Drive Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9709 Direction _____ Street Name Riverview Street Type Drive Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between I-75 & Van Fleet Road
USGS 7.5 Map Name RIVERVIEW USGS Date 1956 Plat or Other Map _____
City / Town (within 3 miles) Riverview In City Limits? yes no unknown County Hillsborough
Township 30S Range 20E Section 19 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-30-20-ZZZ-000002-98660.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367479 Northing 3082874
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1969 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1969 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding
Additions: yes no unknown Date: _____ Nature S elev. shed extension; W elev. porches
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Wayne Hiott (2014); John Thigpen (1990); Opie Willard (1988); John Thigpen (1982); Ronald Martinez

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Wood/Plywood 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. Shed extension 2. Flat extension

Windows (types, materials, etc.)
SHS, vinyl, paired, 6/6; SHS, vinyl, single, 1/1, 3/3

Distinguishing Architectural Features (exterior or interior ornaments)
wide base molding, wood window frames and door surrounds, and overhanging eaves

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Detached garage with gable roof

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

NE ELEV: single panel door with fanlight, beneath shed roof overhang

Porch Descriptions (types, locations, roof types, etc.)

NE/ENTRANCE: open, partial width, beneath a flat roof extension with vinyl porch supports and railing; SW ELEV: open, partial width, beneath a flat roof extension with metal porch supports and screening

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building with wide base molding, wood window frames and door surrounds, and overhanging eaves.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P17097
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS






AERIAL MAP





USGS Riverview
Township 30 South, Range 20 East, Section 19



Copyright © 2013 National Geographic Society, Inc.

1981



HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14682**
Field Date 10-30-2019
Form Date 10-31-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9708 Lorrayne Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9708 Direction _____ Street Name Lorrayne Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Formby Street & Lorrayne Road
USGS 7.5 Map Name RIVERVIEW USGS Date 1956 Plat or Other Map PB 33 / PG 4
City / Town (within 3 miles) Riverview In City Limits? yes no unknown County Hillsborough
Township 30S Range 20E Section 18 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-18-30-20-2RS-000004-00005.0 Landgrant _____
Subdivision Name BYARS RIVERVIEW ACRES Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367482 Northing 3083491
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1957 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1957 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding, windows
Additions: yes no unknown Date: _____ Nature S & W elev gable extensions; carport
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Deborah Bagsby & Azaria Pate (2018); Leeman Hinkle (1990); Dustee Johannsen (1971); Newell Wormwood

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Vinyl 2. _____ 3. _____
Roof Type(s) 1. Gable 2. Shed 3. _____
Roof Material(s) 1. Composition shingles 2. Sheet metal:3V crimp 3. _____
Roof secondary strucs. (dormers etc.) 1. Gable extension 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1, 2/1, 2/2, 1/4

Distinguishing Architectural Features (exterior or interior ornaments)
faux knee braces, decorative trim in gable ends, wood window frames

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

W ELEV: single panel door w/ rectangular light, beneath a gable extension supported by wooden porch supports and railing

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath a gable extension supported by wooden porch supports and railing, accessible by two wooden steps with railing

Condition (overall resource condition): [] excellent [x] good [] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building with faux knee braces, decorative trim in gable ends, wood window frames.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P17097
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS






AERIAL MAP





USGS Riverview
Township 30 South, Range 20 East, Section 18





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14683**
Field Date 10-30-2019
Form Date 10-31-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8012 Formby Street Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from Moccasin Wallow to S of US 301 Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8012 Direction _____ Street Name Formby Street Type Street Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Alsobrook Avenue & Lorraine Road
USGS 7.5 Map Name RIVERVIEW USGS Date 1956 Plat or Other Map PB 33 / PG 4
City / Town (within 3 miles) Riverview In City Limits? yes no unknown County Hillsborough
Township 30S Range 20E Section 18 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-18-30-20-2RS-000004-00003.0 Landgrant _____
Subdivision Name BYARS RIVERVIEW ACRES Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367489 Northing 3083582
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1964 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1964 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding
Additions: yes no unknown Date: _____ Nature Shed roof extensions on W & E Elev.
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Michael & Debra Hernandez (1987); Bendon Investment Co. (1985)

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. _____ 3. _____
Roof Type(s) 1. Gable 2. Shed 3. _____
Roof Material(s) 1. Composition roll 2. Sheet metal:5V crimp 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1, 8/8

Distinguishing Architectural Features (exterior or interior ornaments)
contrasting trim and keystones around windows, overhanging eaves

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed and detached carport

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

W ELEV: obscured, beneath a shed roof extension with metal porch supports and screening

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath a shed roof extension with metal porch supports and screening

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building with contrasting trim and keystones around windows and overhanging eaves.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P17097
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS






AERIAL MAP





USGS Riverview
Township 30 South, Range 20 East, Section 18



APPENDIX C: Demolished Building Letter



Florida's First Choice in Cultural Resource Management

May 11, 2020

Mr. Vincent Birdsong
Supervisor, Florida Master Site File
Division of Historical Resources
500 South Bronough Street
Tallahassee, FL 32399-0250

RE: Historic Resource Status

Dear Mr. Birdsong:

This letter is to inform you that background research and a recent field survey conducted in October 2019 has discovered that two historic resources are no longer extant since they were last recorded. These include a circa 1955 Masonry Vernacular style building located at 9212 Gibsonton Drive (8HI11300) and a circa 1960 Masonry Vernacular style building located at 100100 Gibsonton Drive (8HI11301). Both resources were determined ineligible for listing in the National Register of Historic Places by the State Historic Preservation Officer.

Sincerely,

Savannah Young
Assistant Architectural Historian

APPENDIX D: Survey Log

Ent D (FMSF only) _____



Survey Log Sheet

Florida Master Site File
Version 5.0 3/19

Survey # (FMSF only) _____

Consult *Guide to the Survey Log Sheet* for detailed instructions.

Manuscript Information

Survey Project (name and project phase)

CRAS I-75 (SR 93A) Historic Resources Survey Update, Hillsborough and Manatee Counties, Florida

Report Title (exactly as on title page)

Historic Resources Survey Update Technical Memorandum, I-75 (SR 93A) from Moccasin Wallow Rd to South of US 301, Hillsborough & Manatee Counties, FL WPI Segment No. 419235-2-22-01

Report Authors (as on title page)

1. Marion Almy 3. Kimberly Irby
2. _____ 4. _____

Publication Year 2019

Number of Pages in Report (do not include site forms) 19

Publication Information (Give series, number in series, publisher and city. For article or chapter, cite page numbers. Use the style of *American Antiquity*.)

ACI, Sarasota, 2019 P17097

Supervisors of Fieldwork (even if same as author) Names Marion Almy

Affiliation of Fieldworkers: Organization Archaeological Consultants Inc City Sarasota

Key Words/Phrases (Don't use county name, or common words like *archaeology, structure, survey, architecture, etc.*)

1. I-75 3. _____ 5. _____ 7. _____
2. _____ 4. _____ 6. _____ 8. _____

Survey Sponsors (corporation, government unit, organization, or person funding fieldwork)

Name _____ Organization Florida Dept of Transportation - District 7

Address/Phone/E-mail 11201 North McKinley Drive Tampa, Florida 33612-6456

Recorder of Log Sheet Kimberly M. Irby Date Log Sheet Completed 11-5-2019

Is this survey or project a continuation of a previous project? No Yes: Previous survey #s (FMSF only)

Project Area Mapping

Counties (select every county in which field survey was done; attach additional sheet if necessary)

1. Manatee 3. _____ 5. _____
2. Hillsborough 4. _____ 6. _____

USGS 1:24,000 Map Names/Year of Latest Revision (attach additional sheet if necessary)

1. Name BRANDON Year 1956 4. Name RUSKIN Year 1956
2. Name GIBSONTON Year 1956 5. Name PALMETTO Year 1964
3. Name RIVERVIEW Year 1956 6. Name PARRISH Year 1973

Field Dates and Project Area Description

Fieldwork Dates: Start 10-30-2019 End 10-30-2019 Total Area Surveyed (fill in one) _____ hectares 909.00 acres

Number of Distinct Tracts or Areas Surveyed 6

If Corridor (fill in one for each) Width: _____ meters 300 feet Length: _____ kilometers 25.00 miles

Research and Field Methods

Types of Survey (select all that apply): archaeological architectural historical/archival underwater
 damage assessment monitoring report other(describe): _____

Scope/Intensity/Procedures

background research; field survey; HRSU report prepared

Preliminary Methods (select as many as apply to the project as a whole)

Florida Archives (Gray Building) library research- local public local property or tax records other historic maps LIDAR
 Florida Photo Archives (Gray Building) library-special collection newspaper files soils maps or data other remote sensing
 Site File property search Public Lands Survey (maps at DEP) literature search windshield survey
 Site File survey search local informant(s) Sanborn Insurance maps aerial photography
 other (describe): _____

Archaeological Methods (select as many as apply to the project as a whole)

Check here if **NO** archaeological methods were used.
 surface collection, controlled shovel test-other screen size block excavation (at least 2x2 m) metal detector
 surface collection, uncontrolled water screen soil resistivity other remote sensing
 shovel test-1/4" screen posthole tests magnetometer pedestrian survey
 shovel test-1/8" screen auger tests side scan sonar unknown
 shovel test 1/16" screen coring ground penetrating radar (GPR)
 shovel test-unscreened test excavation (at least 1x2 m) LIDAR
 other (describe): _____

Historical/Architectural Methods (select as many as apply to the project as a whole)

Check here if **NO** historical/architectural methods were used.
 building permits demolition permits neighbor interview subdivision maps
 commercial permits windshield survey occupant interview tax records
 interior documentation local property records occupation permits unknown
 other (describe): _____

Survey Results

Resource Significance Evaluated? Yes No

Count of Previously Recorded Resources 0 Count of Newly Recorded Resources 6

List Previously Recorded Site ID#s with Site File Forms Completed (attach additional pages if necessary)


List Newly Recorded Site ID#s (attach additional pages if necessary)

HI14678-14683

Site Forms Used: Site File Paper Forms Site File PDF Forms

REQUIRED: Attach Map of Survey or Project Area Boundary

SHPO USE ONLY	SHPO USE ONLY	SHPO USE ONLY
Origin of Report: <input type="checkbox"/> 872 <input type="checkbox"/> Public Lands <input type="checkbox"/> UW <input type="checkbox"/> 1A32 # _____ <input type="checkbox"/> Academic <input type="checkbox"/> Contract <input type="checkbox"/> Avocational	<input type="checkbox"/> Grant Project # _____ <input type="checkbox"/> Compliance Review: CRAT # _____	
Type of Document: <input type="checkbox"/> Archaeological Survey <input type="checkbox"/> Historical/Architectural Survey <input type="checkbox"/> Marine Survey <input type="checkbox"/> Cell Tower CRAS <input type="checkbox"/> Monitoring Report	<input type="checkbox"/> Overview <input type="checkbox"/> Excavation Report <input type="checkbox"/> Multi-Site Excavation Report <input type="checkbox"/> Structure Detailed Report <input type="checkbox"/> Library, Hist. or Archival Doc	
<input type="checkbox"/> Desktop Analysis <input type="checkbox"/> MPS <input type="checkbox"/> MRA <input type="checkbox"/> TG <input type="checkbox"/> Other: _____		
Document Destination: <u>Plottable Projects</u>	Plotability: _____	



I-75 from Moccasin Wallow Rd. to US 301
 Township 30 South, Range 20 East, Township 31 South, Range 19 East,
 Township 32 South, Range 19 East, and Township 33 South, Range 18 East
 USGS Palmetto, Parrish, Ruskin, Gibsonton, Riverview, and Brandon
 Hillsborough and Manatee Counties

Historic Resources Survey Update
I-75 (SR 93A) from Moccasin Wallow Road to
South of US 301
Hillsborough and Manatee Counties, Florida,
WPI Segment No. 419235-2-22-01