

HISTORIC RESOURCES SURVEY UPDATE

Interstate 75 (State Road 93A) Project Development and Environment Study

**From south of US 301/State Road 43 to north of Bruce B. Downs
Boulevard/County Road 581**

Hillsborough County, Florida

**WPI Segment Number: 419235-3
ETDM Numbers: 8002 & 14267**

Prepared for:

**Florida Department of Transportation
District Seven
11201 North McKinley Drive
Tampa, Florida 33612-6456**

The environmental review, consultation, and other actions required by applicable federal environmental laws for this project are being, or have been, carried out by FDOT pursuant to 23 U.S.C. § 327 and a Memorandum of Understanding December 14, 2016 and executed by FHWA and FDOT.

April 2020

HISTORIC RESOURCES SURVEY UPDATE

Interstate 75 (State Road 93A) Project Development and Environment Study

**From south of US 301/State Road 43 to north of Bruce B. Downs
Boulevard/County Road 581**

Hillsborough County, Florida

**WPI Segment Number: 419235-3
ETDM Numbers: 8002 & 14267**

DRAFT

Prepared for:

Florida Department of Transportation
District Seven
11201 North McKinley Drive
Tampa, Florida 33612-6456

Prepared by:

Archaeological Consultants, Inc.
8110 Blaikie Court, Suite A
Sarasota, Florida 34240

Marion Almy – Project Manager
Kimberly M. Irby – Architectural Historian

In association with:

WSP USA
2202 West Shore Boulevard, Suite 300
Tampa, Florida 33607

TABLE OF CONTENTS

1. INTRODUCTION.....	1
2. BACKGROUND RESEARCH.....	3
3. SURVEY METHODOLOGY.....	5
4. SURVEY RESULTS.....	6
5. CONCLUSIONS.....	35
6. BIBLIOGRAPHY.....	36

APPENDICES

- Appendix A: SHPO Correspondence
- Appendix B: FMSF Forms
- Appendix C: Demolished Building Letter
- Appendix D: Survey Log

LIST OF FIGURES

Figure 1. Location of the I-75 (SR 93A) study area, Hillsborough County.....	2
Figure 2. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	7
Figure 3. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	8
Figure 4. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	9
Figure 5. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	10
Figure 6. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.....	11

LIST OF TABLES

Table 1. Previously recorded historic Resource Groups within the APE.....	4
Table 2. Previously recorded historic resources within the APE.....	4
Table 3. Newly identified historic resources within the APE.....	6

LIST OF PHOTOS

Photo 1. 10426 Tanner Road (8HI08742), looking south.....	12
Photo 2. 10310 Woodberry Road (8HI14684), looking north.....	13
Photo 3. 2307 Fisher Avenue (8HI14685), looking south.....	14
Photo 4. 2320 Fisher Avenue (8HI14686), looking north.....	15
Photo 5. 2314 Fisher Avenue (8HI14687), looking north-northeast.....	16
Photo 6. 2308 Fisher Avenue (8HI14688), looking north.....	17
Photo 7. 2408 Graves Road (8HI14689), looking south.....	18

LIST OF PHOTOS

Photo 8.	8913 Bowles Road (8HI14872), looking southeast	19
Photo 9.	9119 Bowles Road (8HI14690), looking northeast.	20
Photo 10.	9203 Harney Road (Building #1) (8HI14691), looking southeast.....	21
Photo 11.	9203 Harney Road, looking south. Building #1 (8HI14691) is depicted on the left and Building #2 (8HI14692) is depicted on the far right.....	21
Photo 12.	9203 Harney Road (Building #2) (8HI14692), looking southeast.....	22
Photo 13.	9913 Morris Bridge Road (8HI14693), looking east-southeast.....	23
Photo 14.	9919 Morris Bridge Road (8HI14694), looking east.	23
Photo 15.	9921 Morris Bridge Road (8HI14695), looking east.	24
Photo 16.	9923 Morris Bridge Road (8HI14696), looking east.	25
Photo 17.	9925 Morris Bridge Road (8HI14697), looking northeast.....	26
Photo 18.	10001 Morris Bridge Road (8HI14698), looking east.	27
Photo 19.	10003 Morris Bridge Road (8HI14699), looking east.	28
Photo 20.	10009 Morris Bridge Road (8HI14700), looking east-northeast.	29
Photo 21.	8917 Navajo Avenue (8HI14701), looking south.....	30
Photo 22.	8915 Navajo Avenue (8HI14702), looking southwest.....	31
Photo 23.	8913 Navajo Avenue (8HI14703), looking south.....	32
Photo 24.	8918 Navajo Avenue (8HI14704), looking north.	33
Photo 25.	8916 Navajo Avenue (8HI14705), looking northeast.....	34
Photo 26.	8914 Navajo Avenue (8HI14706), looking north.	35

DRAFT

1. INTRODUCTION

The Florida Department of Transportation (FDOT), District Seven, is conducting a Project Development and Environment (PD&E) Study to evaluate capacity improvements along approximately 18 miles of Interstate 75 (I-75) (State Road [SR] 93A) from south of US 301 (SR 43) to north of Bruce B. Downs Boulevard in Hillsborough County, Florida (**Figure 1**). The design year for the improvements is 2045 (CR 581). The PD&E Study is being conducted concurrently with the PD&E Study for the section of I-75 that extends from Moccasin Wallow Road in Manatee County to south of US 301 in Hillsborough County, Florida (WPI Segment No. 419235-2). The proposed action evaluates the need to provide capacity and operational improvements along approximately 18 miles of I-75 from south of US 301 to north of Bruce B. Downs Boulevard in Hillsborough County, Florida. The Preferred Build Alternative includes widening I-75 within the existing median to include two Express Lanes (EL) in each direction along with operational improvements. The improvements would be constructed on the existing alignment. Right-of-way (ROW) will be required for some interchange improvements, slip ramps to provide access between the general use lanes (GULs) and ELs, stormwater management facilities, and floodplain compensation sites.

Specifically, the Preferred Build Alternative Typical Section includes three, 12-foot GULs with auxiliary lanes in each direction. Inside and outside shoulders will be 12-feet wide. Adjacent to the GULs, within the median, two 12-foot ELs with 12-foot inside and outside shoulders will be included in each direction. The ELs will be separated from the GULs by a 2-foot concrete barrier. Should a multimodal envelope be added to the typical section, it would be placed to the outside on either side of I-75. Interchange improvements will occur at all eight interchanges in the project corridor. While the I-75 at I-4 interchange will see extensive improvements, the remaining interchanges will see minor adjustments to accommodate the preferred build alternative.

Archaeological Consultants, Inc. (ACI) performed a Historic Resources Survey Update (HRSU) for I-75 SR 93A from south of US 301 (SR 43) to north of Bruce B. Downs Boulevard (CR 581) in Hillsborough County, Florida. This effort updates the previous PD&E Cultural Resource Assessment Survey (CRAS) that was prepared by ACI in 2009 and identifies historic resources that were not previously recorded. This current effort also includes the new northern limit of the project from North of the Bruce B. Downs Interchange (ACI 2009a). The previous CRAS report and Case Study Report prepared for the PD&E Study in 2009 were reviewed and approved by the State Historic Preservation Officer (SHPO) (ACI 2009a; 2009b; Kammerer 2010a; 2010b; **Appendix A**). An updated archaeological field survey was not conducted since this survey only focuses on historic resources. The historic area of potential effects (APE) extends 300-feet (ft) from the edge of existing ROW. This APE remains in-keeping with the 2009 CRAS. The current historical/architectural field survey was conducted in October 2019.

The purpose of this HRSU is to locate, identify, and evaluate any resources which have become historic (50 years of age or older) since the previous CRAS (ACI 2009a) within the APE and to assess their significance in terms of eligibility for listing in the National Register of Historic Places (NRHP). All work was conducted to comply with Section 106 of the National Historic Preservation Act of 1966, as amended by Public Law 89-665; the Archaeological and Historic Preservation Act, as amended by Public Law 93-291; Executive Order 11593; and Chapter 267, Florida Statutes (FS). All work was carried out in conformity with Part 2, Chapter 8 (“Archaeological and Historical Resources”) of the FDOT’s PD&E Manual (FDOT 2019), and the Florida Division of Historical Resources’ (FDHR 2003), as well as with the provisions contained in the Chapter 1A-46, Florida Administrative Code (FAC). Principal Investigators meet the Secretary of the Interior’s Historic Preservation Professional



Figure 1. Location of the I-75 (SR 93A) study area, Hillsborough County.

Qualification Standards (48 FR 44716) for archaeology, history, architecture, architectural history, or historic architecture.

The historic/architectural field survey resulted in the identification and evaluation of 24 new historic resources (8HI14684-HI14706; 8HI14872) that are 50 years of age or older (constructed in or prior to 1969); and the identification and re-evaluation of one previously recorded historic resource (8HI08742) within the APE. These include seven Frame Vernacular style buildings (8HI08742; 8HI14685, 8HI14688, 8HI14691, 8HI14692, 8HI14698, & 8HI14700) and 18 Masonry Vernacular style buildings (8HI14684, 8HI14686, 8HI14687, 8HI14689, 8HI14690, 8HI14693-8HI14697; 8HI14699, 8HI14701-8HI14706; 8HI14872) constructed between ca. 1891 and 1969. Three previously recorded historic resources were confirmed as demolished (8HI06900, 8HI11464, and 8HI11471). A Florida Master Site File (FMSF) form was prepared for the 24 newly identified resources, an updated FMSF form was prepared for the previously recorded resource (**Appendix B**), and a letter was prepared for the demolished resources (**Appendix C**).

Out of the 25 identified historic resources, 24 appear ineligible for listing in the NRHP, either individually or as part of a historic district (8HI14684-HI14706; 8HI14872). These resources are common examples of their respective architectural styles without significant historical associations, and therefore, none appear eligible for listing in the NRHP. However, the Tanner Residence located at 10426 Tanner Road (8HI08742), remains eligible at the local level under Criterion C as an example of late 19th to early 20th century rural vernacular architecture.

Specifically, the Tanner Residence was re-evaluated as part of the HRSU to determine if any significant changes occurred since the 2009 CRAS. Despite minor alterations to the exterior, the building appears to retain eligibility under Criterion C as like-materials were used when patching the roof and the majority of visible historic wood windows have been maintained. However, the historic property no longer appears eligible at the local level under Criterion A for its association with early settlement and agricultural practice in Hillsborough County. In the previous survey, the proposed NRHP boundary for this historic resource included the surrounding 1.28-acre parcel and the adjacent 1.42-acre property, totaling 2.7 acres. Associated with the 1.42-acre parcel was the historic orange grove, and the 1.28-acre parcel contained the residence and barn. Since the 2009 update, the associated historic barn and orange grove that contributed to the resource's significance under Criterion A have been demolished and removed. In 2009, a Section 106 Case Study Report was prepared for this resource, and the SHPO concluded that the undertaking would have no adverse effect on the historic property (ACI 2009b; Kammerer 2010b). No additional enhancements from what was coordinated in the 2009 Case Study Report are proposed for this area of I-75; therefore, it appears that the proposed undertaking will still have no adverse effect with any NRHP listed, determined eligible, or potentially eligible resources within the APE.

2. BACKGROUND RESEARCH

Field survey was preceded by background research, which included a check of the digital database of the FMSF in October 2019, and the NRHP, as well as examination of previous studies along and adjacent to the I-75 corridor segment from south of US 301 (SR 43) to north of Bruce B Downs Boulevard. The previous CRAS conducted by ACI in 2009, *Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study from South of US 301 to North of Fletcher Avenue Hillsborough County, Florida*, as well as the *Section 106 Consultation Case Study Report: Evaluation of Effects to the Tanner Residence (8HI08742) located at 10426 Tanner Road* were reviewed (ACI 2009a; Survey No. 17897; ACI 2009b). In-depth historic and prehistoric overviews were included in the PD&E CRAS and are not repeated here.

Historic/architectural background research included a review of the previous I-75 CRAS and memos, the FMSF, and the NRHP. The research indicated 35 historic resources (8HI05085, 8HI05086, 8HI05117, 8HI05958, 8HI06900, 8HI06901, 8HI07839, 8HI07840, 8HI08742, 8HI08743; 8HI11335, 8HI11460-11464, 8HI11466, 8HI11467, 8HI11471, 8HI11472, 8HI11481, 8HI11615, 8HI11616, 8HI11689-8HI11692, 8HI12245-8HI12247, 8HI13604, 8HI13883-8HI13887) were previously recorded within the historic APE (**Tables 1 and 2; Figures 2-6**). These include four linear resources, the Seaboard Railway (8HI11335), the Atlantic Coast/CSX Railway (8HI11481), Harney Flats Canal (8HI13887), US 92 (SR 600/New Tampa Highway (8HI13604) and 31 buildings (8HI05085, 8HI05086, 8HI05117, 8HI05958, 8HI06900, 8HI06901, 8HI07839, 8HI07840, 8HI08742, 8HI08743; 8HI11460-11472, 8HI11615, 8HI11616, 8HI11689-8HI11692, 8HI12245-8HI12247, 8HI13883-8HI13886) constructed between circa (ca.) 1891 and 1965. Of these, 31 (8HI05085, 8HI05086, 8HI05117, 8HI05958, 8HI06900, 8HI06901, 8HI07839, 8HI07840, 8HI08743; 8HI11460-11464, 8HI11466, 8HI11467, 8HI11471, 8HI11472, 8HI11615, 8HI11616, 8HI11689-8HI11692, 8HI12245-8HI12247, 8HI13604, 8HI13883-8HI13886) were evaluated as ineligible for listing in the NRHP by the SHPO. The Atlantic Coast/CSX Railway (8HI11481) and the Seaboard Railway (8HI11335) were evaluated as having insufficient information and Harney Flats Canal (8HI13887) has not been evaluated by the SHPO. The Tanner Residence (8HI08742) was constructed ca. 1891 and was determined eligible for listing in the NRHP by the SHPO in 2010. The resource is significant at the local level under Criterion A for its association with the early settlement of this portion of Hillsborough County, and under Criterion C as a fine example of early 20th century rural vernacular architecture.

Table 1. Previously recorded historic Resource Groups within the APE.

FMSF No.	Site Name	Significant Time Period	Type	SHPO Evaluation	Survey No.
8HI11335	Seaboard Railway	American; 1821-present	Linear Resource	Insufficient Information	25309
8HI11481	Atlantic Coastal/CSX R.R.	American; 1821-present	Linear Resource	Insufficient Information	26284
8HI13604	US 92 / SR 600 / New Tampa Highway	American; 1821-present	Linear Resource	Ineligible	26284
8HI13887	Harney Flats Canal	Boom Times; 1921-1929	Linear Resource	Not Evaluated	24572

Table 2. Previously recorded historic resources within the APE.

FMSF No.	Address/Site Name	Build Date	Style	SHPO Evaluation	Survey No.
8HI05085	6022 Falkenburg Road	1945	Frame Vernacular	Ineligible	17897
8HI05086	6034 Falkenburg Road	1940	Frame Vernacular	Ineligible	17897
8HI05117	6020 Williams Road	1930	Frame Vernacular	Ineligible	7037
8HI05958	9869 US 301	1925	Frame Vernacular	Ineligible	4591
8HI06900	2408 Graves Road	1939	Frame Vernacular	Ineligible	6122
8HI06901	10314 Woodberry Road	1930	Frame Vernacular	Ineligible	6122
8HI07840	8709 Seahawk Lane	1947	Frame Vernacular	Ineligible	17897
8HI08742	10426 Tanner Road	1891	Frame Vernacular	Eligible	17897
8HI08743	10608 Tanner Road	1940	Bungalow	Ineligible	12574
8HI11460	8707 127th Ave	1930	Frame Vernacular	Ineligible	17897
8HI11461	12324 Old Morris Bridge Road	1952	Frame Vernacular	Ineligible	17897
8HI11462	8903 McRae Road	1959	Frame Vernacular	Ineligible	17897

FMSF No.	Address/Site Name	Build Date	Style	SHPO Evaluation	Survey No.
8HI11463	10212 Morris Bridge Road	1958	Masonry vernacular	Ineligible	17897
8HI11464	9016 Copeland Road	1957	Masonry vernacular	Ineligible	17897
8HI11465	9204 US Highway 301	1955	Masonry vernacular	Ineligible	17897
8HI11466	10301 E Sligh Ave	1956	Masonry vernacular	Ineligible	17897
8HI11467	6104 Falkenburg Road	1959	Masonry vernacular	Ineligible	17897
8HI11471	10345 Fisher Road	1935	Frame Vernacular	Ineligible	17897
8HI11472	10308 Woodberry Road	1955	Frame Vernacular	Ineligible	17897
8HI11615	11705 Primrose Lane	1952	Masonry vernacular	Ineligible	18251
8HI11616	11712 Davis Road	1963	Minimal Traditional	Ineligible	18251
8HI11689	9879 US Hwy 301	1956	Frame Vernacular	Ineligible	19174
8HI11690	9915 US Hwy 301	1962	Masonry vernacular	Ineligible	19174
8HI11691	9919 US Hwy 301	1961	Masonry vernacular	Ineligible	19174
8HI11692	10020 US Hwy 301	1956	Masonry vernacular	Ineligible	19174
8HI12245	6026 N Faulkenburg Road	1965	Frame Vernacular	Ineligible	21848
8HI12246	6104 N Faulkenburg Road	1959	Masonry vernacular	Ineligible	21848
8HI12247	6110 N Faulkenburg Road	1964	Masonry vernacular	Ineligible	21848
8HI13883	6115 N Falkenburg Road	1962	Ranch	Ineligible	24572
8HI13884	6121 N Falkenburg Road	1965	Ranch	Ineligible	24572
8HI13885	6122 N Falkenburg Road	1940	Minimal Traditional	Ineligible	24572
8HI13886	10214 E Sligh Ave	1961	Ranch	Ineligible	24572

*Blue highlight denotes NRHP eligible resource.

A review of relevant historic United States Geographical Survey (USGS) quadrangle maps, historic aerial photographs, and the Hillsborough County Property Appraiser's data revealed the potential for 24 new historic resources 50 years of age or older (constructed in 1969 or earlier) within the APE (Henriquez 2019).

3. SURVEY METHODOLOGY

Historic/architectural field methodology consisted of a field survey of the APE to determine and verify the location of all buildings and other historic resources (i.e. bridges, roads, cemeteries) that are 50 years of age or older (built in or prior to 1969), and to establish if any such resources could be determined eligible for listing in the NRHP. The field survey focused on the assessment of existing conditions for all previously recorded historic resources located within the APE, and the presence of unrecorded historic resources within the project area. For each property, photographs were taken, and information needed for the completion of FMSF forms was gathered. In addition to architectural descriptions, each historic resource was reviewed to assess style, historic context, condition, and potential NRHP eligibility. Also, informant interviews would have been conducted, if possible, with knowledgeable persons to obtain site-specific building construction dates and/or possible associations with individuals or events significant to local or regional history.

4. SURVEY RESULTS

As a result of historic field survey, 24 historic resources (8HI14684-HI14706; 8HI14872) were identified, recorded, and evaluated within APE; and one previously recorded historic resource was re-evaluated (8HI08742) (**Table 3; Figures 2-6**). These include seven Frame Vernacular style buildings (8HI08742; 8HI14685, 8HI14688, 8HI14691, 8HI14692, 8HI14698, & 8HI14700) and 18 Masonry Vernacular style buildings (8HI14684, 8HI14686, 8HI14687, 8HI14689, 8HI14690, 8HI14693-8HI14697; 8HI14699, 8HI14701-8HI14706; 8HI14872) constructed between ca. 1891 and 1969. Three previously recorded historic resources were confirmed as demolished (8HI06900, 8HI11464, and 8HI11471). Out of the 25 identified historic resources, 24 appear ineligible for listing in the NRHP, either individually or as part of a historic district (8HI14684-HI14706; 8HI14872). These resources are common examples of their respective architectural styles without significant historical associations, and therefore, none appear eligible for listing in the NRHP. However, the Tanner Residence located at 10426 Tanner Road (8HI08742) remains eligible at the local level under Criterion C as an example of late 19th to early 20th century rural vernacular architecture. Descriptions and photographs of the resources follow, and FMSF forms are contained in **Appendix B**; and a letter was prepared for the demolished resources (**Appendix C**).

Table 3. Newly identified historic resources within the APE.

FMSF No.	Address/Site Name	Build Date	Style/Type	NRHP Eligibility Recommendation
*8HI08742	10426 Tanner Road	1891	Frame Vernacular	Eligible
8HI14684	10310 Woodberry Road	1960	Masonry Vernacular	Ineligible
8HI14685	2307 Fisher Avenue	1930	Frame Vernacular	Ineligible
8HI14686	2320 Fisher Avenue	1957	Masonry Vernacular	Ineligible
8HI14687	2314 Fisher Avenue	1960	Masonry Vernacular	Ineligible
8HI14688	2308 Fisher Avenue	1932	Frame Vernacular	Ineligible
8HI14689	2408 Graves Road	1961	Masonry Vernacular	Ineligible
8HI14872	8913 Bowles Road	1963	Masonry Vernacular	Ineligible
8HI14690	9119 Bowles Road	1962	Masonry Vernacular	Ineligible
8HI14691	9203 Harney Road (Bldg #1)	1966	Frame Vernacular	Ineligible
8HI14692	9203 Harney Road (Bldg #2)	1968	Frame Vernacular	Ineligible
8HI14693	9913 Morris Bridge Road	1960	Masonry Vernacular	Ineligible
8HI14694	9919 Morris Bridge Road	1965	Masonry Vernacular	Ineligible
8HI14695	9921 Morris Bridge Road	1961	Masonry Vernacular	Ineligible
8HI14696	9923 Morris Bridge Road	1960	Masonry Vernacular	Ineligible
8HI14697	9925 Morris Bridge Road	1962	Masonry Vernacular	Ineligible
8HI14698	10001 Morris Bridge Road	1968	Frame Vernacular	Ineligible
8HI14699	10003 Morris Bridge Road	1947	Masonry Vernacular	Ineligible
8HI14700	10009 Morris Bridge Road	1968	Frame Vernacular	Ineligible
8HI14701	8917 Navajo Avenue	1964	Masonry Vernacular	Ineligible
8HI14702	8915 Navajo Avenue	1964	Masonry Vernacular	Ineligible
8HI14703	8913 Navajo Avenue	1962	Masonry Vernacular	Ineligible
8HI14704	8918 Navajo Avenue	1963	Masonry Vernacular	Ineligible
8HI14705	8916 Navajo Avenue	1964	Masonry Vernacular	Ineligible
8HI14706	8914 Navajo Avenue	1963	Masonry Vernacular	Ineligible

*Denotes updated historic resource and blue highlight denotes NRHP eligible resource.




Figure 2. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE. Yellow denotes previously recorded resources and red denotes demolished resources.



Figure 3. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE.




Figure 4. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE. Yellow denotes previously recorded resources; the asterisk indicates an updated status.




Figure 6. Location newly recorded and previously recorded historic resources within the I-75 (SR 93A) corridor APE. Yellow denotes previously recorded resources.



Photo 1. 10426 Tanner Road (8HI08742), looking south.

8HI08742: The Frame Vernacular style building at 10426 Tanner Road was constructed in ca. 1891 (**Photo 1**). The two-story I-house has an irregular plan that rests on a pier foundation (obscured by wooden lattice) and has a wood frame structural system clad in drop siding. The centered gable principal roof and half-hip roof of the first story are covered with 5V crimp sheet metal. A brick chimney is located on the gable wall of the west elevation. The main entryway is on the south elevation through a single wooden door with rectangular paneling within a partial width open porch beneath a half-hip roof supported by turned wooden porch supports and accessed by two wooden steps. Visible windows include a mixture of individual and paired, two-over-two wood double-hung-sash units; individual six-light wood fixed units; and individual, one-over-one metal single-hung-sash units. Distinguishing architectural features include overhanging eaves with boxed rafter tails, centered gable roof, exposed beams in the front gable, wooden trim around windows and doors, turned wooden porch supports, brick chimney, and corner boards. Alterations include patched roofing and replacement windows. Additions include the partial enclosure of the porch on the north elevation, completed in ca. 1920, and a ca. 1960 shed roof addition to the north elevation. A non-historic utility shed is located to the west of the building.

The historic property at 10426 Tanner Road (8HI08742) was previously recorded in 2003 and updated 2008 (ACI/Janus Research 2003; ACI 2009). As a result of the *Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study from South of US 301 to North of Fletcher Avenue Hillsborough County, Florida*, the resource was determined eligible for listing in the NRHP by the SHPO in 2010 (ACI 2009a; Kammerer 2010a). The historic property was determined eligible at the local level under Criterion A for its association with early settlement and agricultural practice in Hillsborough County and under Criterion C as an example of late 19th to early 20th century rural vernacular architecture. In the previous survey, the proposed NRHP boundary for this historic resource included the surrounding 1.28-acre parcel and the adjacent 1.42-acre property, totaling 2.7 acres. Associated with the 1.42-acre parcel was the historic orange grove, and the 1.28-acre parcel contained the residence and barn. Since the 2009 update, the associated historic barn and orange grove that contributed to the resource's significance under Criterion A have been demolished and removed. With the removal of the citrus grove and barn, the Tanner Residence no longer retains the significant physical features that contributed to its historical associations with the broad trends and patterns of the

farming and citrus industries that once characterized late 19th and early 20th century Florida. Therefore, the Tanner Residence no longer appears eligible for listing in the NRHP under Criterion A.

However, the historic property maintains most of its character-defining architectural features and appears to remain significant or NRHP eligible under Criterion C in the area of Architecture. Minor alterations have taken place since the Frame Vernacular style building was updated in 2009, including the patching of a section of the first-story half-hip roof with like materials, the replacement of three visible historic windows, and the boarding up of a centrally located window in the front gable. In-kind materials were used when patching the roof and the majority of visible historic wood windows have been maintained. Despite these alterations, the exterior alterations could easily be changed to return the building to its original historic appearance.



Photo 2. 10310 Woodberry Road (8HI14684), looking north.

8HI14684: The Masonry Vernacular style building at 10310 Woodberry Road was constructed in ca. 1960 (**Photo 2**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system with horizontal plank siding in the gable ends. The front gable roof is covered with standing seam sheet metal. The main entryway is on the south elevation through a single wood panel door within a partial width open porch beneath a gable roof with metal porch supports. Visible windows include a mixture of individual one-over-one, six-over-six, and eight-over-eight vinyl single-hung-sash units. Distinguishing architectural features include a vent in the gable end. Alterations include replacement roofing and windows. An attached one-car carport with rear utility room is located on the west elevation. A utility shed and non-historic detached carport are located on the property. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14684 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 3. 2307 Fisher Avenue (8HI14685), looking south.

8HI14685: The Frame Vernacular style building at 2307 Fisher Avenue was constructed in ca. 1930 (**Photo 3**). The one-story, irregular plan building rests on a pier foundation and has a wood frame structural system clad in vinyl siding. The cross-gabled roof is covered with 5V crimp sheet metal. A stucco chimney is located on the west elevation slope. The main entryway is on the east elevation through a single door beneath an overhanging eave. Visible windows include a mixture of individual and paired six-over-six and eight-over-eight vinyl single-hung-sash units. Distinguishing architectural features include overhanging eaves, window shutters, octagonal gable vent, and corner boards. Alterations include replacement roofing, siding, and windows. A detached garage is located to the south of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14685 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 4. 2320 Fisher Avenue (8HI14686), looking north.

8HI14686: The Masonry Vernacular style building at 2320 Fisher Avenue was constructed in ca. 1957 (**Photo 4**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco. The hip roof is covered with 5V crimp sheet metal. The main entryway is on the south elevation through a single door with a rectangular light within a partial width open porch beneath shed metal roof with a scalloped edging supported by metal porch supports with a decorative scroll pattern. Visible windows include a mixture of individual, one-over-one and four-over-four vinyl single-hung-sash units. Distinguishing architectural features include stucco windowsills and metal porch supports. Alterations include replacement roofing and windows. A non-historic utility shed is located to the northwest of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14686 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 5. 2314 Fisher Avenue (8HI14687), looking north-northeast.

8HI14687: The Masonry Vernacular style building at 2314 Fisher Avenue was constructed in ca. 1960 (**Photo 5**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco. The side gable roof is covered with ribbed sheet metal, while the garage addition has a composition shingle gable roof. A brick chimney is located on the east elevation slope of the principal roof and a concrete block chimney is located on the slope of the garage addition. The main entryway is on the south elevation through a single door with a metal frame screen door within a partial width open porch beneath the principal roof supported by metal porch supports with a decorative scroll pattern. Visible windows include individual, one-over-one metal single-hung-sash units. Distinguishing architectural features include stucco windowsills, shutters, and metal porch supports. Alterations include replacement roofing and windows and additions include an attached wood-frame one-car garage and an attached one-car carport on the east elevation. A gazebo and two utility sheds are located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14687 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 6. 2308 Fisher Avenue (8HI14688), looking north.

8HI14688: The Frame Vernacular style building at 2308 Fisher Avenue was constructed in ca. 1932 (**Photo 6**). The one-story, irregular plan building rests on a continuous foundation and has a wood frame structural system clad in stucco with plywood siding in the gable ends. The cross-gabled roof is covered with composition shingles. The main entryway is on the south elevation through a single door within a full width open porch beneath a half hip roof supported by tapered wooden porch supports on squared stucco piers with a wooden railing. Visible windows include individual, eight-over-eight vinyl single-hung-sash units. Distinguishing architectural features include tapered wooden porch supports on squared stucco piers, overhanging eaves, and stucco trim around the windows. Alterations include replacement roofing, siding, and windows and additions include the south porch and attached one-car garage. A non-historic guest house with attached carport and utility sheds are located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14688 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 7. 2408 Graves Road (8HI14689), looking south.

8HI14689: The Masonry Vernacular style building at 2408 Graves Road was constructed in ca. 1961 (**Photo 7**). The one-story, irregular plan building rests on a continuous concrete block foundation and has a concrete block structural system. The side gable roof over the principal mass and the shed extension are covered with composition shingles. The main entryway is on the north elevation through a single door with a metal frame screen door within a partial width open porch beneath the shed extension supported by metal porch supports with a decorative scroll pattern and matching railing. A wooden ramp extends to the front porch. Visible windows include a mixture of individual, one-over-one metal sliding units and individual three-light metal fixed units. Distinguishing architectural features include stucco windowsills, metal porch supports, and overhanging eaves with boxed rafters. Alterations include replacement roofing and windows; and additions include an attached carport on the east elevation. A ca. 1961 utility shed, a non-historic utility shed, and a non-historic detached carport are located to the south of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14689 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 8. 8913 Bowles Road (8HI14872), looking southeast.

8HI14872: The Masonry Vernacular style building at 8913 Bowles Road was constructed in ca. 1963 (**Photo 8**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in brick veneer. The side gable roof is covered with ribbed sheet metal. The main entryway is on the west elevation through a single door within a partial width incised porch beneath the principal roof. Visible windows include a mixture of individual one-over-one vinyl single-hung-sash units and paired three-stacked metal awning units. Distinguishing architectural features include overhanging eaves with boxed rafter tails and brick windowsills. Alterations include replacement roofing and windows. Additions include an enclosed carport with plywood siding on the north elevation and a finished utility shed on the east elevation. A non-historic Quonset hut and detached carport are located to the east of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14872 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 9. 9119 Bowles Road (8HI14690), looking northeast.

8HI14690: The Masonry Vernacular style building at 9119 Bowles Road was constructed in ca. 1962 (**Photo 9**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system partially clad in brick veneer with plywood siding in the gable ends. The low-pitched cross-gabled roof and shed extension are covered in built-up membrane. The main entryway is on the southwest elevation through an obscured door within a partial width open porch beneath the principal roof supported by metal porch supports with a decorative scroll pattern set into a brick planter. Visible windows include a mixture of individual and paired, one-over-one and two-over-two metal single-hung-sash units; individual, one-over-one vinyl single-hung-sash units; and paired, two-light metal picture units. Distinguishing architectural features include masonry windowsills, brick veneer cladding, metal porch supports, low-pitched roof, and a brick planter wall. Alterations include replacement roofing and windows, and installed window security bars; as well as a large north elevation addition beneath a shed extension. A brick entry planter is located beneath the southwest porch and a non-historic above-ground swimming pool is located to the southwest of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14690 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 10. 9203 Harney Road (Building #1) (8HI14691), looking southeast.



Photo 11. 9203 Harney Road, looking south. Building #1 (8HI14691) is depicted on the left and Building #2 (8HI14692) is depicted on the far right.

8HI14691: The Frame Vernacular style building at 9203 Harney Road was constructed in ca. 1966 (**Photo 10**). The one-story, rectangular plan building rests on a concrete slab foundation and has a wood frame structural system clad in vinyl siding. The side gable roof is covered with ribbed sheet metal. The main entryway is on the north elevation through a single door with an inset six-light fixed window within a partial width incised porch beneath the principal roof overhang supported by squared wooden porch supports and accessed by wooden steps with a wooden railing. Visible windows include a mixture of individual, one-over-one, two-over-two, and eight-over-eight vinyl single-hung-sash units; and an individual one-light vinyl picture unit. Distinguishing architectural features include overhanging eaves with boxed rafters, window shutters, and corner boards. Alterations include replacement roofing, siding, and windows. A non-historic detached carport with a covered walkway which connects to a ca.

1968 Frame Vernacular style building (8HI14692). Other features located on the property include two utility sheds, a swimming pool, and a pole barn (**Photo 11**). Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14691 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 12. 9203 Harney Road (Building #2) (8HI14692), looking southeast.

8HI14692: The Frame Vernacular style building at 9203 Harney Road was constructed in ca. 1955 per property appraiser's data; however, the building first appears on historic aerial photographs in 1968 (Henriquez 2019; USDA 1968) (**Photo 12**). The one-story, irregular plan building rests on a concrete slab foundation and has a wood frame structural system clad in vinyl siding and artificial masonry veneer along the foundation. The front gable roof is covered with ribbed sheet metal, as well as the shed and gable extensions. The main entryway is on the north elevation through a single door with an oval light and sidelights within a full width open porch beneath the principal roof supported by wooden porch supports. Visible windows include a mixture of paired, six-over-six metal single-hung-sash units; and an individual one-light vinyl picture unit. Distinguishing architectural features include overhanging eaves with boxed rafters, window shutters, and corner boards. Alterations include replacement roofing, siding, and windows. Additions include a shed extension on the east elevation and a gable extension on the south elevation. A ca. 1966 Frame Vernacular style building (8HI14691) and a non-historic covered walkway, detached carport, utility sheds, swimming pool, and pole barn are located northeast of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14692 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 13. 9913 Morris Bridge Road (8HI14693), looking east-southeast.

8HI14693: The Masonry Vernacular style building at 9913 Morris Bridge Road was constructed in ca. 1960 (**Photo 13**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco with plywood siding in the gable ends. The cross-gabled roof is covered with composition shingles. The main entryway is on the north elevation and obscured. Visible windows include a mixture of individual and paired, one-over-one vinyl single-hung-sash units. Distinguishing architectural features include stucco windowsills. Alterations include replacement roofing and windows. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14693 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 14. 9919 Morris Bridge Road (8HI14694), looking east.

8HI14694: The Masonry Vernacular style building at 9919 Morris Bridge Road was constructed in ca. 1965 (**Photo 14**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system. The side gable roof is covered with composition shingles. The main entryway is on the west elevation within a partial width open porch beneath the principal roof supported by squared wooden porch supports. Visible windows include a mixture of individual, three-stacked metal awning units and an individual, vinyl picture unit with a central light flanked by four-over-four single-hung-sash units. Distinguishing architectural features include stucco windowsills. Alterations include replacement roofing and windows. A ca. 1965 utility shed, and detached garage are located to the east of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14694 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 15. 9921 Morris Bridge Road (8HI14695), looking east.

8HI14695: The Masonry Vernacular style building at 9921 Morris Bridge Road was constructed in ca. 1961 (**Photo 15**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system with clapboard siding in the gable ends. The cross-gabled roof is covered with ribbed sheet metal. The main entryway is on the south elevation through a single door within a partial width open porch beneath a shed roof supported by metal pole porch supports. Visible windows include a mixture of paired, two-stacked and three-stacked metal awning units. Distinguishing architectural features include stucco windowsills and overhanging eaves with boxed rafter tails. Alterations include replacement roofing. A ca. 1963 detached garage is located to the east of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14695 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 16. 9923 Morris Bridge Road (8HI14696), looking east.

8HI14696: The Masonry Vernacular style building at 9923 Morris Bridge Road was constructed in ca. 1960 (**Photo 16**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco and brick veneer with clapboard siding in the gable ends. The side gable roof is covered with composition shingles, while the flat roof extension is covered with built-up membrane. The main entryway is on the west elevation through a single wood panel door with a metal frame screen door within a partial width open porch beneath a flat roof extension supported by metal porch supports with a decorative scroll pattern. Visible windows include a mixture of individual and paired, four-stacked metal awning units. Distinguishing architectural features include stucco windowsills and brick veneer paneling. Alterations include replacement roofing and additions include a utility room on the south elevation of the attached carport. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14696 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 17. 9925 Morris Bridge Road (8HI14697), looking northeast.

8HI14697: The Masonry Vernacular style building at 9925 Morris Bridge Road was constructed in ca. 1962 (**Photo 17**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system partially clad in brick veneer. The hip roof is covered with composition shingles. The main entryway is on the west elevation through a single door with metal security bar door and sidelights within a partial width open porch beneath the principal roof with concrete block porch supports. Visible windows include a mixture of individual and paired, two-stacked and three-stacked metal awning units and an individual metal picture unit with a central pane flanked by three-stacked lights. Distinguishing architectural features include overhanging eaves, brick planter box, and brick windowsills. Alterations include replacement roofing. An attached two-car carport with rear utility room is located on the south elevation. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14697 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 18. 10001 Morris Bridge Road (8HI14698), looking east.

8HI14698: The Frame Vernacular style building at 10001 Morris Bridge Road was constructed in ca. 1947 per property appraiser's data; however, the building first appears on historic aerial photographs in 1968 (Henriquez 2019; USDA 1968) (**Photo 18**). The one-story, irregular plan building rests on a pier foundation that is obscured by vinyl skirting. The building has a wood frame structural system clad in vinyl siding; and the open porch rests on a continuous concrete block foundation. The cross-gabled roof is covered with composition shingles. The main entryway is on the west elevation through a single door within a partial width open porch beneath a gable roof with square wooden porch supports and accessed by three steps with a wooden railing. Visible windows include a mixture of individual and paired, one-over-one vinyl single-hung-sash units and an individual single-light vinyl picture unit. Distinguishing architectural features include overhanging eaves and wood trim around the windows and doors. Alterations include replacement roofing, siding, and windows. A non-historic utility shed is located immediately adjacent to the south elevation. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14698 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 19. 10003 Morris Bridge Road (8HI14699), looking east.

8HI14699: The Masonry Vernacular style building at 10003 Morris Bridge Road was constructed in ca. 1947 (**Photo 19**). The two-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco with plywood siding in the gable ends. The hip roof, gable extensions, and shed roof extension are covered with ribbed sheet metal. The main entryway is on the west elevation through a single door with oval light within a partial width open porch beneath a shed roof extension with screening and a stone half wall. Visible windows include individual and paired, one-over-one vinyl single-hung-sash units. Distinguishing architectural features include stucco windowsills, stone veneer shutters, and artificial masonry veneer trim around the windows. Alterations include replacement roofing, windows, and trim; and additions include two front gable extensions connected by a shed extension on the west elevation and an addition along the east elevation. A non-historic swimming pool is located to the east of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14699 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 20. 10009 Morris Bridge Road (8HI14700), looking east-northeast.

8HI14700: The Frame Vernacular style building at 10009 Morris Bridge Road was constructed in ca. 1968 (**Photo 20**). The one-story, irregular plan building rests on a concrete slab foundation and has a wood frame structural system clad in stucco and artificial masonry veneer along the base. The side gable roof is covered with composition shingles, while the carport addition has a standing seam metal shed roof. The main entryway is on the west elevation through a single door with arched light within a partial width incised porch beneath the principal roof with screening and an artificial masonry veneer half wall. Visible windows include a mixture of individual, one-over-one vinyl single-hung-sash units and an individual one-light vinyl picture unit. Distinguishing architectural features include wooden trim around the windows, artificial masonry veneer, and overhanging eaves with boxed rafter tails. Alterations include replacement roofing, windows, and siding and additions include an attached two-car carport on the west elevation. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14700 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 21. 8917 Navajo Avenue (8HI14701), looking south.

8HI14701: The Masonry Vernacular style building at 8917 Navajo Avenue was constructed in ca. 1964 (**Photo 21**). The one-story, L-shaped plan building rests on a concrete slab foundation and has a concrete block structural system with plywood siding in the gable ends. The cross-gabled roof is covered with composition shingles. The main entryway is on the north elevation through a single wood panel door with a fanlight within a partial width incised porch beneath the principal roof with square wooden porch supports. Visible windows include a mixture of individual and paired, two-over-two metal single-hung-sash units. Distinguishing architectural features include overhanging eaves with boxed rafter tails and rusticated stucco windowsills. Alterations include replacement roofing and the partial enclosure of the carport. An attached carport with plywood siding and a wooden lattice inset is located on the north elevation. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14701 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 22. 8915 Navajo Avenue (8HI14702), looking southwest.

8HI14702: The Masonry Vernacular style building at 8915 Navajo Avenue was constructed in ca. 1964 (**Photo 22**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco with plywood siding in the gable ends. The cross-gabled roof is covered with composition shingles. The main entryway is on the north elevation through a single door with a full-light storm door within a partial width open porch beneath a gable roof supported by squared wooden porch supports. Visible windows include a mixture of individual, one-over-one vinyl single-hung-sash units and an individual one-over-one vinyl sliding unit. Distinguishing architectural features include overhanging eaves with boxed rafter tails, stucco windowsills, stucco trim around the windows, and stucco quoins. Alterations include replacement roofing, windows, and the application of stucco quoins. Additions include a ca. 1993 stucco chimney located on the slope of the north elevation and an addition on the south elevation. A one-car garage with segmental garage door is located on the north elevation. A non-historic utility shed is located to the south of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14702 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 23. 8913 Navajo Avenue (8HI14703), looking south.

8HI14703: The Masonry Vernacular style building at 8913 Navajo Avenue was constructed in ca. 1962 (**Photo 23**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in brick veneer and stucco. The hip roof is covered with composition shingles. The main entryway is on the north elevation through a single door within a partial width open porch beneath a hip roof supported by squared wooden porch supports. Visible windows include a mixture of individual and paired, one-over-one vinyl single-hung-sash units. Distinguishing architectural features include overhanging boxed eaves and brick windowsills. Alterations include replacement roofing and windows. An attached one-car garage with segmental garage door is located on the north elevation. A non-historic utility shed is located immediately adjacent to the south elevation. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14703 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 24. 8918 Navajo Avenue (8HI14704), looking north.

8HI14704: The Masonry Vernacular style building at 8918 Navajo Avenue was constructed in ca. 1963 (**Photo 24**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco. The hip roof is covered with composition shingles. A stucco chimney is located on the slope of the north elevation. The main entryway is on the south elevation through a single door with an oval light and metal security bar screen door within a partial width open porch beneath a hip roof supported by metal porch supports with a decorative scroll pattern. Visible windows include individual, one-over-one vinyl sliding units. Distinguishing architectural features include overhanging boxed eaves, stucco windowsills, and stucco quoins. Alterations include replacement roofing, windows, and the application of stucco quoins. An attached one-car carport with rear utility room and decorative scroll pattern metal supports and railing is located on the south elevation. A non-historic utility shed is located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14704 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 25. 8916 Navajo Avenue (8HI14705), looking northeast.

8HI14705: The Masonry Vernacular style building at 8916 Navajo Avenue was constructed in ca. 1964 (**Photo 25**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco, brick veneer, and plywood siding in the side gable ends. The cross-gabled roof is covered with composition shingles, while the shed extension is covered with 3V crimp sheet metal. The main entryway is on the south elevation through a single door with a $\frac{3}{4}$ -light storm door within a partial width open porch beneath a gable roof supported by metal porch supports with a decorative floral pattern. Visible windows include a mixture of individual and paired, two-over-two metal single-hung-sash units. Distinguishing architectural features include metal porch supports, overhanging eaves with boxed rafter tails, and stucco windowsills. Alterations include replacement roofing and additions include a shed roof extension on the east elevation. A non-historic utility shed, and above-ground swimming pool are located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14705 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 26. 8914 Navajo Avenue (8HI14706), looking north.

8HI14706: The Masonry Vernacular style building at 8914 Navajo Avenue was constructed in ca. 1963 (**Photo 26**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in brick veneer, stucco, and vinyl siding in the gable ends. The cross-gabled roof is covered with composition shingles. The main entryway is on the south elevation through a single door within a partial width open porch beneath a gable roof supported by fluted column porch supports. Visible windows include a mixture of individual and paired, one-over-one vinyl single-hung-sash units. Distinguishing architectural features include fluted columns, overhanging eaves with boxed rafter tails, and brick windowsills. Alterations include replacement roofing, windows, and enclosing the carport with plywood siding to form a one-car garage; and an addition was placed on the north elevation. A non-historic swimming pool and utility sheds are located to the north of the building. Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8HI14706 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.

5. CONCLUSIONS

The I-75 (SR 93A) HRSU resulted in the identification and evaluation of 24 historic resources (8HI14684-8HI14706; 8HI14872); and the identification and re-evaluation of one previously recorded historic resource (8HI08742). These include seven Frame Vernacular style buildings (8HI08742; 8HI14685, 8HI14688, 8HI14691, 8HI14692, 8HI14698, & 8HI14700) and 18 Masonry Vernacular style buildings (8HI14684, 8HI14686, 8HI14687, 8HI14689, 8HI14690, 8HI14693-8HI14697; 8HI14699, 8HI14701-8HI14706; 8HI14872) constructed between ca. 1891 and 1969. Out of the 25 identified historic resources, 24 appear ineligible for listing in the NRHP, either individually or as part of a historic district (8HI14684-8HI14706; 8HI14872). These resources are common examples of their respective architectural styles without significant historical associations, and therefore, none appear eligible for listing in the NRHP. However, the Tanner Residence located at 10426 Tanner Road (8HI08742) remains eligible at the local level under Criterion C as an example of late 19th to early 20th century rural vernacular architecture. In addition, three previously recorded historic resources were confirmed as demolished (8HI06900, 8HI11464, and 8HI11471).

Based on the results of the background research and field survey, the historic property located at 10426 Tanner Road (8HI08742) remains eligible at the local level under Criterion C as an example of late 19th to early 20th century rural vernacular architecture. This resource was re-evaluated as part of the HRSU to determine if any significant changes occurred since the 2009 CRAS. Despite minor alterations to the exterior, the building appears to retain eligibility under Criterion C as like-materials were used when patching the roof and the majority of visible historic wood windows have been maintained. However, the historic property no longer appears eligible at the local level under Criterion A for its association with early settlement and agricultural practice in Hillsborough County since the associated historic barn and orange grove that contributed to the resource's significance when it was previously evaluated have been demolished and removed. In 2009, a Section 106 Case Study Report was prepared for this resource, and the SHPO concluded that the undertaking would have no adverse effect on the historic property (ACI 2009b; Kammerer 2010b). No additional enhancements from what was coordinated in the 2009 Case Study Report are proposed for this area of I-75; therefore, it appears that the proposed undertaking will still have no adverse effect with any NRHP listed, determined eligible, or potentially eligible resources within the APE.

6. BIBLIOGRAPHY

Archaeological Consultants, Inc. (ACI)

- 2009a Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study from South of US 301 to North of Fletcher Avenue, Hillsborough County, Florida. ACI, Sarasota. Survey No. 17897.
- 2009b Project Development and Environment (PD&E) Study I-75 from South of US 301 to North of Fletcher Avenue; Section 106 Case Study Report Evaluation of Effects to the Turner Residence (8HI08742) located at 10426 Tanner Road, Hillsborough County, Florida. ACI, Sarasota.
- 2011 Cultural Resource Assessment Survey Addendum Technical Memorandum State Road 93A (I-75) from South of SR 582 (Fowler Avenue) to North of CR 581 (Bruce B Downs Boulevard), Hillsborough County, Florida. ACI, Sarasota. Survey No. 18251.
- 2012 Cultural Resource Assessment Survey Technical Memorandum of Three SMF's and a Historic Resources Survey Update of US 301 (SR 41) from South of the Tampa Bypass Canal to North of Fowler Avenue, Hillsborough County, Florida. ACI, Sarasota. Survey No. 19174.
- 2014 Cultural Resource Assessment Survey I-4 Project Development and Environment (PD&E) Study from east of 50th Street to Polk Parkway in Hillsborough and Polk Counties, Florida. ACI, Sarasota. Survey No. 21848.
- 2017 Cultural Resource Assessment Survey Technical Memorandum Update, State Road (SR 93A (I-75) SB Off-Ramp from S of Bypass Canal to EB/WB I-4 Hillsborough County, Florida. ACI, Sarasota. Survey No. 24572.
- 2016 Cultural Resource Assessment Survey Update SR 600 (US 92) PD&E Study Reevaluation from East of I-4 to East of County Line Road in Hillsborough County, Florida. ACI, Sarasota. Survey No. 26284.

Archaeological Consultants, Inca. (ACI) and Janus Research

- 2003 Cultural Resource Assessment Survey Report Florida High Speed Rail Authority Project Development and Environment (PD&E) Study from Tampa to Orlando, Hillsborough, Polk, Osceola, and Orange Counties, Florida. Survey No. 12574.

Austin, Robert J.

- 2000 Survey Report for the FGT Company Proposed Bayside Lateral Reroute, Hillsborough County, Florida. Survey No. 6122.

Florida Department of Transportation (FDOT)

- 2019 *Project Development and Environment Manual, Part 2, Chapter 8, Archaeological and Historical Resources*. FDOT, Tallahassee.

Florida Division of Historical Resources (DHR)

- n.d. Florida Master Site File Form Information.
- 2003 *Cultural Resource Management Standards and Operational Manual*. FDHR, Tallahassee.

Henriquez, Bob

- 2019 Hillsborough County Property Appraisers, Hillsborough County.

Janus Research

- 1996 Cultural Resource Assessment Survey for US 301 from Interstate 4 (I-4) to Fowler Avenue in Hillsborough County, Florida. Survey No. 4591.

Jones, Lucy D.

- 2018 South Ybor Historic Resources Survey, City of Tampa, Hillsborough County, Florida. Survey No. 25309.

Kammerer, Laura

- 2010a SHPO Concurrence Letter, DHR Project File No.: 2009-7642, Cultural Resource Assessment Survey Interstate 75 (I-75) Project Development and Environment (PD&E) Study I-75 from South of US 301 to North Fletcher Avenue, Hillsborough County, Florida. ACI, Sarasota.
- 2010b SHPO Concurrence Letter, DHR Project File No.: 2010-2934(B), Draft Section 106 Case Study Report, I-75 from South of US 301 to North Fletcher Avenue, Hillsborough County, Florida. ACI, Sarasota.

Stokes, Anne V.

- 2002 Addendum Report to the Florida Gas Transmission Company Bayside Lateral Modifications, Hillsborough County, Florida. Survey No. 7037.

United States Geological Survey (USGS)

- 1956 Brandon, Fl (Photo Revised, 1987)
- 1974 Thonotosassa, Fl (Photo Revised, 1987)
- 1974 Lutz, Fl (Photo Revised, 1987)
- 1973 Wesley Chapel, Fl (Photo Revised, 1987)

United States Department of Agriculture (USDA)

- 1968 Aerial Photograph. 1-21-68, BQF-3JJ-203. PALMM, Gainesville.
- 1968 Aerial Photograph. 1-21-68, BQF-3JJ-255. PALMM, Gainesville.

WSP

- 2020 I-75 from US 301 to north of Bruce B. Downs Boulevard Project Description, electronically received February 14.

DRAFT

APPENDIX A: SHPO Correspondence



Florida Department of Transportation

11201 N. McKinley Drive Tampa, FL 33612-6456 Phone (813) 975-6000 1-800-226-7220

CHARLIE CRIST
GOVERNOR

STEPHANIE C. KOPELOUSOS
SECRETARY

May 10, 2010

Ms. Linda Anderson
Federal Highway Administration
Florida Division
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

RE: WPI Segment No: 419235 3; FAP No. N/A
I-75 from South of US 301 to North of Fletcher Avenue PD&E Study
Hillsborough County

Dear Ms. Anderson:

Enclosed you will find two copies of the Draft Section 106 Consultation Case Study Report (April 2010) that was prepared to evaluate effects to the Tanner Residence (8H18742). This residence was determined eligible for listing in the National Register of Historic Places (NRHP) in the Cultural Resource Assessment Survey (CRAS) that was prepared for the above referenced Project Development and Environment (PD&E) Study. The NRHP boundaries included the two parcels containing the residence, a barn, and orange groves. The CRAS was submitted to your office for review and coordination with the State Historic Preservation Officer (SHPO). In a letter dated January 19, 2010, the SHPO concurred that the Tanner Residence was eligible for NRHP listing and they looked forward to continuing coordination regarding the effects, if any, that the proposed undertaking would have on this historic property. The enclosed Draft Section 106 Consultation Case Study Report provides a project description; discussion of alternatives evaluated, including the Recommended Build Alternative and preferred alternative modifications; and an evaluation of effects.

The Recommended Build Alternative proposes widening I-75 mainly to the inside within the existing median plus a 9-foot widening to the outside on both sides of I-75. The Recommended Build Alternative also included making modifications to the existing interchanges. The Tanner Residence is located directly west of the western right of way line of I-75, between the Dr. Martin Luther King, Jr. Boulevard (SR 574) and I-4 (SR 400) interchanges. The Recommended Build Alternative interchange Option A would have required right-of-way taking from the Tanner Residence property for the modified I-4 interchange. Two avoidance concepts were evaluated for this interchange that would avoid right-of-way impacts to the Tanner Residence property. Avoidance Concept No. 2 was selected since it did not eliminate movements between Dr. Martin Luther King, Jr.

Ms. Linda Anderson
WPI Segment No: 419235 3; FAP No. N/A
I-75 from South of US 301 to North of Fletcher Avenue PD&E Study
May 10, 2010
Page 2

Boulevard and I-4 that were provided in the original PD&E Recommended Build Alternative; whereas, Avoidance Concept No. 1 would have eliminated those movements. Avoidance Concept No. 2 also utilizes a gravity wall along the eastern boundary of the Tanner Residence property to allow for the realignment of the mainline and ramps without any right-of-way impacts to the NRHP-eligible resource.

Preliminary assessments on the vertical alignment of I-75 and the ramps in the vicinity of the Tanner Residence indicate that both I-75 and the ramps would be below the existing ground elevation of the Tanner Residence property and should therefore not have visual or aesthetic effects to this historic resource. As a result of the proposed modifications, the new PD&E Recommended Build Alternative will not involve direct use impacts to the Tanner Residence. In addition, the characteristics which qualify the historic resource for inclusion in the NRHP will not be altered. In conclusion, the Criteria of Adverse Effect, as contained in 36 CFR 800.5(a)(1) were applied to the Tanner Residence for the new Recommended Build Alternative. As a result, the proposed undertaking will have no adverse effect on the NRHP-eligible Tanner Residence.

The two Draft Section 106 Consultation Case Study Reports are provided for your review and coordination with the SHPO. Provided your office concurs that the proposed undertaking will have no adverse effect on the NRHP-eligible Tanner Residence, please coordinate with the SHPO for their review and comment. If you have any questions, please do not hesitate to call me at (813) 975-6173.

Sincerely,



Manuel Santos
Project Manager

MS/rss
Enclosure

cc: Nahir DeTizio (FHWA)
George Hadley (FHWA)
Roy Jackson (FDOT CEMO)
Roberto Gonzalez (FDOT D7)
Rebecca Spain Schwarz (PBS&J)
Panos Kontses (PB Americas)
Joan Deming (ACI)

Ms. Linda Anderson
WPI Segment No: 419235 3; FAP No. N/A
I-75 from South of US 301 to North of Fletcher Avenue PD&E Study
May 10, 2010
Page 3

The FHWA finds the attached Draft Section 106 Consultation Case Study Report complete and sufficient and ___ approves / ___ does not approve the above recommendations and findings.

The FHWA requests the SHPO's opinion on the sufficiency of the attached report and the SHPO's opinion on the recommendations and findings contained in this cover letter and in the comment block below.

FHWA Comments:

/s/
Martin C. Knopp
Division Administrator
Florida Division
Federal Highway Administration

Date

The Florida State Historic Preservation Officer finds the attached Draft Section 106 Consultation Case Study Report complete and sufficient and concurs with the recommendations and findings provided in this cover letter for SHPO/DHR Project File Number _____.

Scott M. Stroh, III
State Historic Preservation Officer
Florida Division of Historical Resources

Date



FLORIDA DEPARTMENT OF STATE

Dawn K. Roberts

Interim Secretary of State

DIVISION OF HISTORICAL RESOURCES

Ms. Linda Anderson
Federal Highway Administration
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

June 30, 2010

RE: DHR No.: 2010-2934/Received by DHR: June 21, 2010
Project: Draft Section 106 Case Study Report, I-75 from South of US 301 to North of
Fletcher Avenue PD&E Study
County: Hillsborough County
FPID No. 419235-3-22-01

Dear Ms. Anderson

This office received and reviewed the above-referenced project in accordance with Section 106 of the National Historic Preservation Act of 1966 as amended, 36 CFR Part 800: Protection of Historic Properties, and Chapter 267, *Florida Statutes*. It is the responsibility of the State Historic Preservation Officer to advise and assist, as appropriate, Federal and State agencies in carrying out their historic preservation responsibilities; to cooperate with agencies to ensure that historic properties are taken into consideration at all levels of planning and development; and to consult with the appropriate agencies in accordance with the National Historic Preservation Act of 1966 as amended, on undertakings that may affect historic properties.

The Tanner Residence (8HI8742) is a rural residential property that was erected at its current location circa 1891. In a letter dated January 19, 2010, this office concurred with the Federal Highway Administration's (FHWA) determination that the resource was eligible for listing in the National Register of Historic Places (NRHP) (DHR No.: 2009-7642). Because the above-listed project has the potential to adversely impact an NRHP-eligible property, an effort was undertaken to develop and evaluate alternatives that could avoid or minimize adverse effects to the Tanner Residence (8HI8742). The submitted draft report outlines this effort.

The report noted that the Recommended Build Alternative Interchange Option A would have required the acquisition of right-of-way from the Tanner Residence's parcel. Two avoidance options that would avoid/minimize adverse effects to the Tanner Residence were therefore evaluated and Avoidance Concept No. 2 was selected because it allowed for movement between Dr. Martin Luther King Jr. Boulevard and I-4 as provided in the original PD&E Recommended Build Alternative and it allowed for the realignment of the mainline and ramps without any right-

500 S. Bronough Street • Tallahassee, FL 32399-0250 • <http://www.flheritage.com>

Director's Office
850.245.6300 • FAX: 245.6436

Archaeological Research
850.245.6444 • FAX: 245.6452

Historic Preservation
850.245.6333 • FAX: 245.6437

Ms. Linda Anderson
DHR No.: 2010-2934
June 30, 2010
Page 2

of-way impacts to the NRHP-eligible resource. After a review of the report, FHWA concurred with its recommendation that the Avoidance Concept No. 2 would not adversely affect the historic Tanner Residence (8HI8742).

After a review of the submitted report, this agency concurs with the assertion that the Avoidance Concept No. 2 would avoid direct affects to the NRHP-eligible Tanner Residence (8HI8742). However, we request that plan sheets that depict the proposed 5'-0" gravity in relation to the Tanner Residence's location be submitted to us for review so that we may more accurately determine the visual impacts, if any, that the project could have on the resource. Once this office receives the requested information, we should be able to quickly complete our review of the draft case study. If you have any questions concerning our comments, please contact Jennifer Ross, Compliance Review Architectural Historian, via electronic mail jross@dos.state.fl.us, or at 850.245.6333.

Sincerely,

A handwritten signature in cursive script that reads "Laura A. Kammerer". The signature is written in black ink and is positioned over a large, light gray "DRAFT" watermark.

Laura A. Kammerer
Deputy State Historic Preservation Officer
For Review and Compliance

PC: Manuel Santos, FDOT District 7, Tampa
Roy Jackson, FDOT CEMO, Tallahassee/#5500
Rebecca-Span Schwartz, PBS&J, Tampa
Nahir DeTitzio, FHWA, Tallahassee



Florida Department of Transportation

11201 N. McKinley Drive Tampa, FL 33612-6456 Phone (813) 975-6000 1-800-226-7220

CHARLIE CRIST
GOVERNOR

STEPHANIE C. KOPELOUSOS
SECRETARY

July 22, 2010

Ms. Laura Kammerer
Deputy State Historic Preservation Officer
For Review and Compliance
Florida Division of Historical Resources
500 S. Bronough Street
Tallahassee, FL 32399-0250

RE: WPI Segment No: 419235 3; FAP No. N/A
I-75 from South of US 301 to North of Fletcher Avenue PD&E Study
Hillsborough County

Dear Ms. Kammerer,

In your June 30, 2010 letter you have indicated that you have received the Draft Section 106 Consultation Case Study Report (CSR) for the Tanner Residence (8HI8742) from the Federal Highway Administration (FHWA) and that the FHWA has determined that the Avoidance Concept No. 2 would not adversely affect this property. You have also requested plan sheets that depict the proposed 5-foot-high gravity wall in relation to the Tanner Residence's location in order to complete your review of the Section 106 Consultation CSR.

Please be advised that design plans and cross sections, which would provide the information you requested, were not produced as part of the Project Development and Environment (PD&E) Study. Preparation of design plans and cross sections requires extensive surveying to identify ROW and surrounding ground elevations, which typically takes place during the design phase of the project. Only conceptual plans were produced during the PD&E Study with use of current aerial photography, Hillsborough County Property Appraiser's maps, USGS topographic information, and the I-75 As-Built plans. Based on the review of this information, we have determined the following:

- Avoidance Concept No. 2 is feasible and will not require any land acquisition for the Tanner Residence property (as stated in the second paragraph of Section 6.1, page 29, of the CSR)
- The I-75 mainline and ramps will be lower than the Tanner Residence property and, therefore, there should be no visual/aesthetic effects to the property (as stated in the last sentence of Section 6.2, page 30, of the CSR). The estimated

5-foot-high gravity wall will be visible from the ramps and the I-75 mainline but not from the Tanner Residence property.

Also, as noted in Section 6.3 (page 32) of the CSR, based on the noise and air quality analyses performed for this property, there should be no appreciable increases in noise levels and only minor air quality effects resulting from the proposed improvements.

Since design plans and cross sections are not available at this time, we can add a commitment statement in Section 7.0 (Conclusions) for the Final Section 106 Consultation CSR stating that "design plans for the I-75 improvements in the vicinity of the Tanner Residence, when available during the design phase, will be provided to SHPO for review." Please let us know if the above information satisfactorily addresses your request or if you would like to have a consultation conference call.

If you have any questions, please do not hesitate to call me at (813) 975-6173.

Sincerely,



Manuel Santos
Project Manager

MS/rss

cc: Linda Anderson (FHWA)
Nahir DeTizio (FHWA)
George Hadley (FHWA)
Roy Jackson (FDOT CEMO)
Roberto Gonzalez (FDOT D7)
Rebecca Spain Schwarz (PBS&J)
Panos Kontses (PB Americas)
Joan Deming (ACI)



FLORIDA DEPARTMENT OF STATE

Dawn K. Roberts

Interim Secretary of State

DIVISION OF HISTORICAL RESOURCES

Ms. Linda Anderson
Federal Highway Administration
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

August 30, 2010

RE: DHR No.: 2010-2934(B)/Received by DHR: August 26, 2010
Project: Draft Section 106 Case Study Report, I-75 from South of US 301 to North of
Fletcher Avenue PD&E Study
County: Hillsborough County
FPID No. 419235-3-22-01

Dear Ms. Anderson

This office received and reviewed the above-referenced project in accordance with Section 106 of the National Historic Preservation Act of 1966 as amended, 36 CFR Part 800: Protection of Historic Properties, and Chapter 267, *Florida Statutes*. It is the responsibility of the State Historic Preservation Officer to advise and assist, as appropriate, Federal and State agencies in carrying out their historic preservation responsibilities; to cooperate with agencies to ensure that historic properties are taken into consideration at all levels of planning and development; and to consult with the appropriate agencies in accordance with the National Historic Preservation Act of 1966 as amended, on undertakings that may affect historic properties.

On June 21, 2010 the Florida Department of Transportation (FDOT) submitted a draft Section 106 Case Study for the Tanner Residence (8HI8742), a National Register of Historic Places-eligible property within the above-listed project's area of potential effects. The draft case study noted that the Recommended Build Alternative Interchange Option A would have required the acquisition of right-of-way from the Tanner Residence's parcel. Two avoidance options that would avoid/minimize adverse effects to the Tanner Residence were therefore evaluated and Avoidance Concept No. 2 was selected because it allowed for movement between Dr. Martin Luther King Jr. Boulevard and I-4 as provided in the original PD&E Recommended Build Alternative and it allowed for the realignment of the mainline and ramps without any right-of-way impacts to the NRHP-eligible resource. After a review of the report, FHWA concurred with its recommendation that the Avoidance Concept No. 2 would not adversely affect the historic Tanner Residence (8HI8742). After a review of the submitted report, this agency concurred with the assertion that the Avoidance Concept No. 2 would avoid direct affects to the NRHP-eligible Tanner Residence 8HI8742). However, we requested that plan sheets that depict (the proposed 5'-0" gravity in relation to the Tanner Residence's location be submitted to us for review so that

500 S. Bronough Street • Tallahassee, FL 32399-0250 • <http://www.flheritage.com>

Director's Office
850.245.6300 • FAX: 245.6436

Archaeological Research
850.245.6444 • FAX: 245.6452

Historic Preservation
850.245.6333 • FAX: 245.6437

Ms. Linda Anderson
DHR No.: 2010-2934
August 30, 2010
Page 2

we may more accurately determine the visual impacts, if any, that the project could have on the resource. In response to our request, the FDOT noted in letter dated July 22, 2010 that because the design plans and cross sections for the project are not available at this time, they would add a commitment statement in Section 7.0 (Conclusions) of the Final Section 106 Case Study report that states that “design plans for the I-75 improvements in the vicinity of the Tanner Residence, when available during the design phase, will be provided to the SHPO for review.” This office feels that this commitment satisfactorily addresses our initial request.

If you have any questions concerning our comments, please contact Jennifer Ross, Compliance Review Architectural Historian, via electronic mail jrross@dos.state.fl.us, or at 850.245.6333.

Sincerely,



Laura A. Kammerer
Deputy State Historic Preservation Officer
For Review and Compliance

PC: Manuel Santos, FDOT District 7, Tampa
Roy Jackson, FDOT CEMO, Tallahassee/#5500
Rebecca-Span Schwartz, PBS&J, Tampa
Nahir DeTizio, FHWA, Tallahassee

From: Ross, Jennifer R. [JRRoss@dos.state.fl.us]
Sent: Wednesday, October 06, 2010 12:42 PM
To: Linda.Anderson@dot.gov
Cc: kirk.bogen@dot.state.fl.us; Spain-Schwarz, Rebecca; Nahir.DeTizio@dot.gov; many.santos@dot.state.fl.us; Jackson, Roy; Kammerer, Laura; Yates, Brian
Subject: I-75 / Tanner Residence

Follow Up Flag: Follow up
Flag Status: Flagged

Hello Linda,

In a letter dated 6/30/2010, this office requested that design plans for the I-75 improvements in the vicinity of the NRHP-eligible Tanner Residence (8HI8742) be provided to us for review so that we might determine the visual impacts, if any, that the project could have on the resource (DHR No.: 2010-2934B). In response to our request, the FDOT noted in letter dated July 22, 2010 that they would add a commitment statement in Section 7.0 (Conclusions) of the Final Section 106 Case Study report that states that "design plans for the I-75 improvements in the vicinity of the Tanner Residence, when available during the design phase, will be provided to the SHPO for review." However, during a 10/5/2010 teleconference with FHWA and FDOT staff provided a verbal description of the wall's location in relation to the eligible Tanner Residence (8HI8742) to this agency. As a result of this discussion, our office finds that the project will have no adverse effects, either direct or indirect, on the NRHP-eligible Tanner Residence (8HI8742). Feel free to call or email me if you have any questions or comments.

Cheers,

Jennifer R. Ross, M.S.
Architectural Historian
Transportation Compliance Review Program
Division of Historical Resources
Florida Department of State

500. S. Bronough Street
R.A. Gray Building
Tallahassee, Florida 32306-0250

(850) 245-6333 (phone)
1-800-847-7278 (toll free)
(850) 245-6437 (fax)

Please take a few minutes to provide feedback on the quality of service you received from our staff. The Florida Department of State values your feedback as a customer. Dawn K. Roberts, Florida Interim Secretary of State, is committed to continuously assessing and improving the level and quality of services provided to you. Simply click on the link to the "DOS Customer Satisfaction Survey." Thank you in advance for your participation.
[DOS Customer Satisfaction Survey](#)



FLORIDA DEPARTMENT OF STATE
Kurt S. Browning
Secretary of State
DIVISION OF HISTORICAL RESOURCES

Linda Anderson
Federal Highway Department
545 John Knox Road, Suite 200
Tallahassee, Florida 32303

January 19, 2010

RE: DHR Project File No.: 2009-7635 and 2009-7642
WPI Segment No.: 419235-2 and 419235-3
Project: *I-75 from Moccasin Wallow Road to South of US 301 PD&E Study and
I-75 South of US 301 to North Fletcher Avenue PD&E Study*
County: Manatee and Hillsborough

Dear Ms. Anderson:

This office received and reviewed the above referenced project in accordance with Section 106 of the National Historic Preservation Act of 1966 as amended, 36 CFR Part 800: Protection of Historic Properties, and Chapter 267, Florida Statutes. It is the responsibility of the State Historic Preservation Officer to advise and assist, as appropriate, Federal and State agencies in carrying out their historic preservation responsibilities; to cooperate with agencies to ensure that historic properties are taken into consideration at all levels of planning and development; and to consult with the appropriate agencies in accordance with the National Historic Preservation Act of 1966 as amended, on undertakings that may affect historic properties.

The current submittal includes two Project and Development and Environmental (PD&E) studies for the portion of I-75 that extends from Moccasin Wallow Road to US 301 (WPI Segment No.: 419235-2) and from US 301 to North Fletcher Avenue (WPI Segment No.: 419235-3). The project includes the widening of I-75 in both directions within the above-stated limits in addition to the modification of existing interchanges.

Background research for the portion of the project that extends along I-75 between Moccasin Wallow Road and US 301 (WPI Segment No.: 419235-2) noted that there were 10 previously-identified archaeological sites (8HI409, 8HI478, 8HI479, 8HI480, 8HI524, 8HI525, 8HI526, 8HI527, 8HI532, and 8MA136) one previously-identified historic structure (8HI11302), and one previously-identified resource group (8MA1337) within the project's area of potential effects (APE). One of the previously-identified archaeological sites, 8HI480, was determined to be eligible for listing in the National Register of Historic Places (NRHP) by this office in 1979, while the remaining nine archaeological sites have yet to be evaluated by the SHPO. The previously-recorded resource group and historic structure were determined to be ineligible for the NRHP by

500 S. Bronough Street • Tallahassee, FL 32399-0250 • <http://www.flheritage.com>

Director's Office
850.245.6300 • FAX: 245.6436

Archaeological Research
850.245.6444 • FAX: 245.6452

Historic Preservation
850.245.6333 • FAX: 245.6437

this office. As a result of the field survey, evidence of only three of the previously-recorded archaeological sites (8HI478, 8HI524, and 8HI532) was located within the project's APE. The field survey also determined that 8HI11302, the previously-identified historic structure within the APE, was no longer extant. Newly-identified resources documented within the APE as a result of the fieldwork included eight buildings (8HI11295-8HI11302), one archaeological site (8HI11359), and two archaeological occurrences (AOs). The report concluded that none of the historic-age architectural resources within the APE were eligible for listing in the NRHP because each lacked architectural and historic import. Similarly, the portion of the three previously-recorded archaeological sites within the APE (8HI478, 8HI524, and 8HI532), the newly-recorded archaeological site 8HI11359, and the two AO's were evaluated and considered to be insignificant and thus ineligible for inclusion in the NRHP. A table in the report noted that the portions of archaeological sites 8HI409, 8HI479, 8HI480, 8HI525, 8HI526, 8HI527, and 8MA136 were ineligible for listing in the NRHP because no evidence of these previously-identified sites was found during the field study.

Background research for the portion of the project that extends along I-75 between US 301 and North Fletcher Avenue (WPI Segment No.: 419235-3) noted that there were 28 previously-identified archaeological sites and eight previously-identified historic structures within the project APE. Of the 36 previously-identified cultural resources, twelve (archaeological sites numbers 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479) were determined to be eligible for listing in the NRHP by this office. As a result of the field survey, evidence of only ten of the 28 previously-recorded archaeological sites (8HI99, 8HI472, 8HI476A, 8HI476B, 8HI507, 8HI510, and 8HI5431, 8HI5432, 8HI5434, and 8HI5926) and all of the eight previously-recorded historic structures were located within the project's APE and reevaluated. Newly-identified resources documented within the APE as a result of the fieldwork include 15 buildings and two resource groups (8HI11460-11472 and 8HI11481-11482) as well as two AOs. The report found that only one of the documented historic structures, the *Tanner Residence* (8HI8742), was eligible for listing in the NRHP. The report also concluded that the newly-recorded AOs and the portions of the 10 previously-recorded archaeological sites found within the APE were ineligible for listing in the NRHP. A table in the report noted that the portions of the remaining 18 previously-identified archaeological sites were ineligible for listing in the NRHP because no evidence of these sites was found during the field study.

After a review of the submitted reports, this office concurs with the Florida Department of Transportation's determination that the *Tanner Residence* (8HI8742) is eligible for listing in the NRHP and looks forward to continuing coordination regarding the affects, if any, that the proposed undertaking will have on this historic property.


The reports noted that the Florida Master Site Files indicated the presence of 13 archaeological sites within the project's APE that had been previously determined to be NRHP eligible by this

Ms. Linda Anderson
DHR Project File No.: 2009-7635 and 2009-7642
January 19, 2010
Page 3

office (sites 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI480, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479). After the field study, the reports concluded that the portion of each of these sites within the APE was ineligible because very little or no cultural material was located as a result of subsurface testing. Please note, for the sake of clarification, that this office seldom confers a dual eligibility designation to a single site (i.e., a site is either *eligible* or *not eligible* for the NRHP). This office therefore finds that sites 8HI99, 8HI450, 8HI472, 8HI473, 8HI476A, 8HI476B, 8HI480, 8HI483, 8HI485, 8HI507, 8HI509, 8HI510, and 8HI1479 should maintain their status as NRHP eligible, but finds that the project will have *no adverse affect* [as per 36 C.F.R. Part 800, § 800.5(b)] on the sites due to the location of the proposed project and the lack of cultural material present within the project's APE.

If there are any questions concerning our comments or recommendations, please contact Jennifer Ross, Architectural Historian, by phone at 850.245.6333, or via electronic mail at jross@dos.state.fl.us.

Sincerely,



Laura A. Kammerer
Deputy State Historic Preservation Officer
For Review and Compliance

PC: Bob Gleason, FDOT District 5, Deland
Roy Jackson, FDOT CEMO, Tallahassee/#5500

DRAFT

APPENDIX B: FMSF Forms



HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI08742**
Field Date 10-29-2019
Form Date 11-11-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 10426 Tanner Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 10426 Direction _____ Street Name Tanner Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Eric Slane Lane & I-75
USGS 7.5 Map Name BRANDON USGS Date 1956 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 5 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-05-29-20-ZZZ-000002-37240.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369469 Northing 3097086
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1891 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1891 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature Partially enclosed N porch; N shed roof
Architect (last name first): _____ Builder (last name first): Tanner, John
Ownership History (especially original owner, dates, profession, etc.)
Barbara J. & Frederick L. Patrick (1983) - grandson of builder/original owner John Tanner; John Edmond Tanner

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 2
Exterior Fabric(s) 1. Drop siding 2. _____ 3. _____
Roof Type(s) 1. _____ 2. Shed 3. centered gable
Roof Material(s) 1. Sheet metal:5V crimp 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. half-hip

Windows (types, materials, etc.)
DHS, wood, single, paired, 2/2; Fixed, wood, single, 6-light; SHS, metal, single, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
See continuation sheet.

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____		
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____			
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 1 Chimney Material(s): 1. Brick 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Piers 2.
Foundation Material(s): 1. Obscured 2.

Main Entrance (stylistic details)

S/ELEV: single door w/ rectangular paneling, beneath a half-hip roof w/ turned wooden porch supports

Porch Descriptions (types, locations, roof types, etc.)

S ENTRANCE: open, partial width, beneath a half-hip roof supported by turned wooden porch supports and accessed by two wooden steps; W/ELEV: open, partial width, beneath a shed roof supported by squared wooden porch supports

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

See continuation sheet.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [x] yes [] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

See continuation sheet.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

- 1. Architecture 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.

CONTINUATION SHEET

The Frame Vernacular style building at 10426 Tanner Road was constructed in circa (c.) 1891. The two-story I-house has an irregular plan that rests on a pier foundation (obscured by wooden lattice) and has a wood frame structural system clad in drop siding. The centered gable roof is covered with 5V crimp sheet metal, as well as the half-hip roof of the first story. A brick chimney is located on the gable wall of the west elevation. The main entryway is on the south elevation through a single wooden door with rectangular paneling within a partial width open porch beneath a half-hip roof supported by turned wooden porch supports and accessed by two wooden steps. Visible windows include a mixture of individual and paired, two-over-two wood double-hung-sash units; individual six-light wood fixed units; and individual, one-over-one metal single-hung-sash units. Distinguishing architectural features include overhanging eaves with boxed rafter tails, centered gable roof, exposed beams in the front gable, wooden trim around windows and doors, turned wooden porch supports, brick chimney, and corner boards. Alterations include patched roofing and replacement windows. Additions include the partial enclosure of the porch on the north elevation, completed in c. 1920, and a c. 1960 shed roof addition to the north elevation. A non-historic utility shed is located to the west of the building.

The property at 10426 Tanner Road (8HI08742) was previously recorded in 2003 and 2008 (ACI/Janus Research 2003; ACI 2009). As a result of the *Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study from South of US 301 to North of Fletcher Avenue Hillsborough County, Florida*, the resource was determined eligible for listing in the NRHP by the SHPO in 2010 (ACI 2009). The property was determined eligible at the local level under Criterion A for its association with early settlement and agricultural practice in Hillsborough County and under Criterion C as a fine example of late 19th to early 20th century rural vernacular architecture. In the previous survey, the proposed NRHP boundary for this historic resource included the surrounding 1.28-acre parcel and the adjacent 1.42-acre property, totaling 2.7 acres. Associated with the 1.42-acre parcel was the historic orange grove, and the 1.28-acre parcel contained the residence and barn. Since the 2009 update, the associated historic barn and orange grove that contributed to the resource's significance under Criterion A have been demolished and removed (**Photos 1 – 3**). With the removal of the citrus grove and barn, the Tanner Residence no longer retains the significant physical features that contributed to its historical associations with the broad trends and patterns of the farming and citrus industries that once characterized late 19th and early 20th century Florida. Therefore, the Tanner Residence no longer appears eligible for listing in the NRHP under Criterion A.

Overall, the historic property maintains most of its character-defining architectural features and appears to remain significant/NRHP eligible under Criterion C in the area of Architecture. Minor alterations have taken place since the Frame Vernacular style building was updated in 2009, including the patching of a section of the first-story half-hip roof with like materials, the replacement of three visible historic windows, and the boarding up of a centrally located window in the front gable. In-kind materials were used when patching the roof and the majority of visible historic wood windows have been maintained. Despite these alterations, the exterior alterations could easily be changed to return the building to its original historic appearance.

CONTINUATION SHEET



Photo 1. 1957 aerial photograph depicting the 8HI08742 property. Included in the yellow boundary line is the Frame Vernacular style building (left), the historic barn (right); and the red boundary line includes the historic orange grove (USDA 1957).




Photo 2. 2008 aerial photograph depicting the 8HI08742 property. Included in the yellow boundary line is the Frame Vernacular style building (left), the historic barn (right); and the red boundary line includes the historic orange grove (FDOT 2008).

CONTINUATION SHEET



Photo 3. 2017 aerial photograph depicting the 8HI08742 property, including the Frame Vernacular style building. The remaining historic orange grove to the left of the building has been removed and the historic barn has been demolished (FDOT 2017). Yellow line denotes the remaining 1.28-acre boundary; dashed red line represents the 1.42-acre parcel that contained the orange grove and is no longer included as part of the NRHP boundary.

REFERENCES

Archaeological Consultants, Inc. (ACI)

- 2009 Cultural Resource Assessment Survey Project Development and Environment (PD&E) Study from South of US 301 to North of Fletcher Avenue, Hillsborough County, Florida. ACI, Sarasota.

Archaeological Consultants, Inc. (ACI) and Janus Research

- 2003 Cultural Resource Assessment Survey Report Florida High Speed Rail Authority Project Development and Environment (PD&E) Study from Tampa to Orlando, Hillsborough, Polk, Osceola, and Orange Counties, Florida. ACI, Sarasota.

Florida Department of Transportation (FDOT)

- 2008 Aerial Photograph. HIL2008_70011. APLUS, Tallahassee.
2017 Aerial Photograph. HIL2017_470011. APLUS, Tallahassee.

United States Department of Agriculture (USDA)

- 1957 Aerial Photograph. 3-23-57, BQF-3T-136. PALMM, Gainesville.



PHOTOGRAPHS




DRAFT






AERIAL MAP





USGS Brandon
Township 29 South, Range 20 East, Section 5





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14684**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 10310 Woodberry Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 10310 Direction _____ Street Name Woodberry Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Woodberry Road & I-75
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map PB 26 / PG 1
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 17 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-17-29-20-2D2-000000-00033.0 Landgrant _____
Subdivision Name Fisher's Farms Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369280 Northing 3092691
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1960 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1960 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Ashton realty & Investments, LLC (2014); Woodberry Properties, LLC (2005); Ernest Lee Miller, Jr (1984); Bernice B. Miller

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. Horizontal plank 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Sheet metal:standing seam 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1, 6/6, 8/8

Distinguishing Architectural Features (exterior or interior ornaments)
vent in gable end

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
c. 1968 utility shed and non-historic detached carport

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Slab 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details) S ELEV: single door, beneath a gable roof w/ metal porch supports

Porch Descriptions (types, locations, roof types, etc.) S ENTRANCE: open, partial width, beneath a gable roof

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource A one-story Masonry Vernacular style building w/ plywood siding in gable ends and a carport w/ a rear utility room.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed) The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.) 1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1 2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites) 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14685**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 2307 Fisher Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 2307 Direction _____ Street Name Fisher Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Fisher Avenue & Fisher Lane
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map PB 26 / PG 1
City / Town (within 3 miles) Brandon In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 17 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-17-29-20-2D2-000000-00019.1 Landgrant _____
Subdivision Name Fisher's Farms Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369608 Northing 3093295
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1930 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1930 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding, windows
Additions: yes no unknown Date: _____ Nature Enclosed porch
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Deborah Corey (2012); Donna Lambert (1999); John & Starr Allen (1997); Ryan David Gregory (1994); James Shrewsbury (1989); Pamela Shrewsbury

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Vinyl 2. _____ 3. _____
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Sheet metal:5V crimp 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, paired, 6/6, 8/8

Distinguishing Architectural Features (exterior or interior ornaments)
overhanging eaves, window shutters, octagonal gable vent, corner boards, and stucco chimney

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
c.1957 detached garage

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 1 Chimney Material(s): 1. Stucco 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Piers 2.
Foundation Material(s): 1. Obscured 2.

Main Entrance (stylistic details)
E ELEV: single door, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource
A one-story Frame Vernacular style building with decorative shutters, corner boards, and a stucco chimney within the principal roof.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)
The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)
1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents
1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14686**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 2320 Fisher Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 2320 Direction _____ Street Name Fisher Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Fisher Avenue & Fisher Lane
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map PB 26 / PG 1
City / Town (within 3 miles) Brandon In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 17 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-17-29-20-2D2-000000-00002.1 Landgrant _____
Subdivision Name Fisher's Farms Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369545 Northing 3093353
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1957 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1957 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Diane Abney (2004); Esther Clarice Eady (1981); Esther & Robert Eady (1970); J.H. Cannington, Sr.

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. _____ 3. _____
Roof Type(s) 1. Hip 2. _____ 3. _____
Roof Material(s) 1. Sheet metal:5V crimp 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1, 4/4

Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, metal porch supports

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

S ELEV: single door w/ rectangular light, beneath a scalloped metal awning

Porch Descriptions (types, locations, roof types, etc.)

S ENTRANCE: open, partial width, beneath a scalloped metal awning supported by metal porch supports w/ decorative scroll pattern

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building with a scalloped metal porch awning and scalloped, fixed metal window awnings.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
| <input checked="" type="checkbox"/> other methods (describe) <u>USDA historic aerial photographs (PALMM)</u> | | | |

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14687**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 2314 Fisher Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 2314 Direction _____ Street Name Fisher Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Fisher Avenue & Fisher Lane
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map PB 26 / PG 1
City / Town (within 3 miles) Brandon In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 17 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-17-29-20-2D2-000000-00002.2 Landgrant _____
Subdivision Name Fisher's Farms Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369588 Northing 3093371
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1960 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1960 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address: _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature Attached garage and carport
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
J.M. & Lorena Hampton

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. Other 3. Metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, metal, single, paired, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
stucco windowsills, shutters, and metal porch supports

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic gazebo and two utility sheds

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 2 Chimney Material(s): 1. Brick 2. Concrete block
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

S ELEV: single door w/ metal frame screen door, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

S ENTRANCE: open, partial width, beneath the principal roof supported by metal porch supports w/ decorative scroll pattern

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building with shutters, stucco window sills, and a wood frame attached one-car garage and attached open carport.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

- 1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM
FLORIDA MASTER SITE FILE
Version 5.0 3/19

Site#8 HI14688
Field Date 10-30-2019
Form Date 11-6-2019
Recorder #

[X] Original
[] Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the Guide to Historical Structure Forms for detailed instructions.

Site Name(s) (address if none) 2308 Fisher Avenue
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs
National Register Category (please check one) [X]building []structure []district []site []object
Ownership: []private-profit []private-nonprofit [X]private-individual []private-nonspecific []city []county []state []federal []Native American []foreign []unknown

LOCATION & MAPPING

Address: 2308 Fisher Avenue
Cross Streets (nearest / between) Fisher Avenue & Fisher Lane
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map PB 26 / PG 1
City / Town (within 3 miles) Brandon In City Limits? []yes []no [X]unknown County Hillsborough
Township 29S Range 20E Section 17 1/4 section: []NW []SW []SE []NE Irregular-name:
Tax Parcel # U-17-29-20-2D2-000000-00002.0 Landgrant
Subdivision Name Fisher's Farms Block Lot
UTM Coordinates: Zone []16 [X]17 Easting 369617 Northing 3093352
Other Coordinates: X: Y: Coordinate System & Datum
Name of Public Tract (e.g., park)

HISTORY

Construction Year: 1932 []approximately []year listed or earlier [X]year listed or later
Original Use Residence, private From (year): 1932 To (year): CURR
Current Use From (year): To (year):
Other Use From (year): To (year):
Moves: []yes [X]no []unknown Date: Original address:
Alterations: [X]yes []no []unknown Date: Nature Roofing, siding, windows
Additions: [X]yes []no []unknown Date: Nature S porch, garage
Architect (last name first): Builder (last name first):
Ownership History (especially original owner, dates, profession, etc.)
Ramon Morrell & Perfecta Ruiz (2009); Dawna McMahon (2006); Tim Braswell (2006); Tampa Investing Group, Inc (2005); Buddy Butler (1996); Frances Cooper

Is the Resource Affected by a Local Preservation Ordinance? []yes []no [X]unknown Describe

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Wood/Plywood 3.
Roof Type(s) 1. Cross-gabled 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.
Windows (types, materials, etc.)
SHS, vinyl, single, 8/8

Distinguishing Architectural Features (exterior or interior ornaments)
Tapered wooden porch supports on squared stucco piers, overhanging eaves, stucco trim around windows

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic guest house w/ attached carport and utility sheds

Table with 3 columns: DHR USE ONLY, OFFICIAL EVALUATION, DHR USE ONLY. Contains fields for NR List Date, Owner Objection, SHPO - Appears to meet criteria for NR listing, and NR Criteria for Evaluation.

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Continuous 2.
Foundation Material(s): 1. Obscured 2.

Main Entrance (stylistic details)

S ELEV: single door, beneath a half hip roof

Porch Descriptions (types, locations, roof types, etc.)

S/ENTRANCE: open, full width, beneath a half hip roof supported by tapered wooden porch supports on squared stucco piers w/ wooden railing

Condition (overall resource condition): []excellent []good [x]fair []deteriorated []ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building with an attached garage addition with sectional garage door.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x]FMSF record search (sites/surveys) []library research []building permits []Sanborn maps
[]FL State Archives/photo collection []city directory []occupant/owner interview []plat maps
[x]property appraiser / tax records []newspaper files []neighbor interview []Public Lands Survey (DEP)
[]cultural resource survey (CRAS) []historic photos []interior inspection []HABS/HAER record search
[x]other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? []yes [x]no []insufficient information
Appears to meet the criteria for National Register listing as part of a district? []yes [x]no []insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14689**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 2408 Graves Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 2408 Direction _____ Street Name Graves Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) _____
USGS 7.5 Map Name BRADENTON USGS Date 1956 Plat or Other Map _____
City / Town (within 3 miles) Brandon In City Limits? yes no unknown County Hillsborough
Township 29S Range 20E Section 17 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-17-29-20-ZZZ-000002-50790.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 369613 Northing 3093803
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1961 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1961 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature Attached carport
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Allan Peter LaFever (2013); Maggie Greene (1979); Robert & Frances DuBose

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. Shed extension 2. _____
Windows (types, materials, etc.)
Sliding, metal, single, 1/1; Fixed, metal, single, 3-light
Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, metal porch supports, and overhanging eaves with boxed rafters
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
utility sheds and detached carport

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____	
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. 3.
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Continuous 2.
Foundation Material(s): 1. Concrete Block 2.

Main Entrance (stylistic details)

N ELEV: single door w/ metal frame screen door, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

N/ENTRANCE: open, partial width, beneath the principal roof supported by metal porch supports with decorative scroll pattern and matching railing

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ a partially screened carport addition.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Bradenton
Township 29 South, Range 20 East, Section 17





HISTORICAL STRUCTURE FORM
FLORIDA MASTER SITE FILE
Version 5.0 3/19

Site#8 HI14690
Field Date 10-29-2019
Form Date 11-6-2019
Recorder #

[X] Original
[] Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the Guide to Historical Structure Forms for detailed instructions.

Site Name(s) (address if none) 9119 Bowles Road Multiple Listing (DHR only)
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only)
National Register Category (please check one) [X]building []structure []district []site []object
Ownership: []private-profit []private-nonprofit [X]private-individual []private-nonspecific []city []county []state []federal []Native American []foreign []unknown

LOCATION & MAPPING

Street Number 9119 Direction Street Name Bowles Street Type Road Suffix Direction
Address:
Cross Streets (nearest / between) Harney Road & Bowles Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map
City / Town (within 3 miles) Tampa In City Limits? []yes []no [X]unknown County Hillsborough
Township 28S Range 20E Section 19 1/4 section: []NW []SW []SE []NE Irregular-name:
Tax Parcel # U-19-28-20-ZZZ-000002-11340.0 Landgrant
Subdivision Name Block Lot
UTM Coordinates: Zone []16 [X]17 Easting 367561 Northing 3101663
Other Coordinates: X: Y: Coordinate System & Datum
Name of Public Tract (e.g., park)

HISTORY

Construction Year: 1962 []approximately []year listed or earlier [X]year listed or later
Original Use Residence, private From (year): 1962 To (year): CURR
Current Use From (year): To (year):
Other Use From (year): To (year):
Moves: []yes [X]no []unknown Date: Original address
Alterations: [X]yes []no []unknown Date: Nature Roofing, windows, window security bars
Additions: [X]yes []no []unknown Date: Nature N Elev.
Architect (last name first): Builder (last name first):
Ownership History (especially original owner, dates, profession, etc.)
Philip Wetter (2011); Sasha Brooks (2007); Jason Wynne (2006); Dana Beauchamp (2004); E. Levinar (1990); B. Levinar (1982); L. Anderson (1973); Keith Londagin

Is the Resource Affected by a Local Preservation Ordinance? []yes []no [X]unknown Describe

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. Brick 3. Wood/Plywood
Roof Type(s) 1. Cross-gabled 2. 3.
Roof Material(s) 1. Built-up 2. 3.
Roof secondary strucs. (dormers etc.) 1. Shed extension 2.

Windows (types, materials, etc.)
SHS, metal, individual, paired, 1/1, 2/2; SHS, vinyl, single, 1/1; Picture, metal, paired, 2-light

Distinguishing Architectural Features (exterior or interior ornaments)
masonry windowsills, brick veneer cladding, metal porch supports, low-pitched roof, and a brick planter wall

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Brick entry planter, non-historic above-ground swimming pool

Table with 3 columns: DHR USE ONLY, OFFICIAL EVALUATION, DHR USE ONLY. Contains fields for NR List Date, Owner Objection, SHPO evaluation, and NR Criteria for Evaluation.

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Slab 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

SW ELEV: obscured door, beneath the principal roof supported by metal porch supports w/ decorative scrolling

Porch Descriptions (types, locations, roof types, etc.)

SW/ENTRANCE: open, partial width, beneath beneath the principal roof supported by metal porch supports w/ decorative scrolling set into a brick planter

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ a large shed extension addition on the north elevation.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

- 1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1 2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites) 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14691**
Field Date 10-29-2019
Form Date 11-12-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9203 Harney Road (Building #1) Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Address: Street Number 9203 Direction _____ Street Name Harney Street Type Road Suffix Direction _____
Cross Streets (nearest / between) I-75 & Harney Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Thonotosassa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11320.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367720 Northing 3101793
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1966 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1966 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Bruce MacNeel (1988); Bruce Guimares (1982); Sandra Lee Pratt (1981); Bruce Guimares (1978); Laura Oates (1978); Alice Cameron

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Rectangular Number of Stories 1
Exterior Fabric(s) 1. Vinyl 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Other 2. _____ 3. Metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1, 2/2, 8/8; Picture, vinyl, single, one-light

Distinguishing Architectural Features (exterior or interior ornaments)
Overhanging eaves w/ boxed rafter tails, shutters, corner boards

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic detached carport w/ covered walkway to c.1968 Frame Vernacular (8HI14691); non-historic utility sheds, swimming pool, and pole barn

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info		Date _____	Init. _____
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no		Date _____	
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

N/ELEV: single door w/ 6-light inset, beneath the principal roof overhang accessed by wooden steps with a wooden railing

Porch Descriptions (types, locations, roof types, etc.)

N/ENTRANCE: incised, partial width, beneath the principal roof overhang supported by squared wooden porch supports w/ railing and accessed by wooden steps w/ railing

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building has vinyl siding.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14692**
Field Date 10-29-2019
Form Date 11-12-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9203 Harney Road (Building #2) Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Address: 9203 Harney Road
Street Number Direction Street Name Street Type Suffix Direction
Cross Streets (nearest / between) I-75 & Harney Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Thonotosassa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11320.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367685 Northing 3101770
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1968 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1968 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding, windows
Additions: yes no unknown Date: _____ Nature E Elev, S Elev
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Bruce MacNeel (1988); Bruce Guimares (1982); Sandra Lee Pratt (1981); Bruce Guimares (1978); Laura Oates (1978); Alice Cameron

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Vinyl 2. Artif masonry veneer 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Other 2. _____ 3. Metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. Flat extension 2. Gable extension

Windows (types, materials, etc.)
SHS, metal, paired, 6/6; Picture, vinyl, single, one-light

Distinguishing Architectural Features (exterior or interior ornaments)
Overhanging eaves w/ boxed rafter tails, shutters

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Covered walkway to c.1966 Frame Vernacular (8HI14691) and non-historic detached carport; non-historic utility sheds, swimming pool, and pole barn

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____	
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)
N ELEV: single door w/ oval light and sidelights, beneath the principal roof supported by wood porch supports

Porch Descriptions (types, locations, roof types, etc.)
N/ENTRANCE: incised, full width, beneath the principal roof supported by wood porch supports

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource
A one-story Frame Vernacular style building with a large shed extension addition on the E elevation and a large gable addition on the S elevation.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)
The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)
1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents
1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors,
Source: Esri, DigitalGlobe, GeoEye, Earthstar
Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID,
IGN, and the GIS User Community, 2017



USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14693**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9913 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9913 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Morris Bridge Road & Jeanine Lane
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11140.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367183 Northing 31021175
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1960 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1960 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Elaine & Robert Price (2011); John & Hallie Williams

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Wood/Plywood 3. _____
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____
Windows (types, materials, etc.)
SHS, vinyl, single, paired, 1/1
Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____		
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____			
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____
 Structural System(s): 1. Concrete block 2. _____ 3. _____
 Foundation Type(s): 1. Slab 2. _____
 Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

N ELEV: obscured

Porch Descriptions (types, locations, roof types, etc.)

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building that is obscured from the ROW.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- FMSF record search (sites/surveys) library research building permits Sanborn maps
 FL State Archives/photo collection city directory occupant/owner interview plat maps
 property appraiser / tax records newspaper files neighbor interview Public Lands Survey (DEP)
 cultural resource survey (CRAS) historic photos interior inspection HABS/HAER record search
 other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient information
 Appears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. _____ 3. _____ 5. _____
 2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
 Document description Files, photos, research, documents File or accession #'s P19150.1
 2) Document type _____ Maintaining organization _____
 Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
 Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
 (address / phone / fax / e-mail)

Required Attachments

- ① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
 ② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
 ③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
 Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14694**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9919 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9919 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Morris Bridge Road & Hervel Circle
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11150.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 3671147 Northing 3102238
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1965 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1965 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Marjorie Kuczvara (2006); Marjorie Maniglia (1985); Norman Almand

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. _____ 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____
Windows (types, materials, etc.)
Awning, metal, single, 3 stacked; picture, vinyl, single, central light flanked by 4/4
Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
c.1965 utility shed and detached garage

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	<input type="checkbox"/> Owner Objection	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____
		KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____	
		NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)		

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Slab 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

W ELEV: obscured door, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath the principal roof supported by squared wooden porch supports

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource

A Masonry Vernacular style building with a side gable roof.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors, Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community, 2017



USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14695**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9921 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Address: Street Number 9921 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Cross Streets (nearest / between) Morris Bridge Road & Hervel Circle
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11160.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367127 Northing 3102271
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1961 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1961 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
William & Gracie McGraw (1996); Bertha Durk (1982); Kenneth White

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. Clapboard 3. _____
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Other 2. _____ 3. Metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____
Windows (types, materials, etc.)
Awning, metal, paired, 2 stacked, 3 stacked
Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, overhanging eaves w/ boxed rafter tails
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
c. 1963 detached garage

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____	
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Concrete, Generic 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details) S ELEV: single door, beneath a shed roof supported by metal pole porch supports

Porch Descriptions (types, locations, roof types, etc.) S/ENTRANCE: open, partial width, beneath a shed roof supported by metal pole porch supports

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous Narrative Description of Resource A Masonry Vernacular style building w/ clapboard siding in the gable ends.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed) The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.) 1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1 2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites) 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14696**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9923 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9923 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Hervel Circle & Lanway Drive
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11170.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367119 Northing 3102302
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1960 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1960 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing
Additions: yes no unknown Date: _____ Nature Utility room
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Constance Hackworth & Alfonso Massaro (1991); Joseph Martin & Beverly McLemore (1985); Joseph Martin

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Clapboard 3. Brick
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. Built-up 3. _____
Roof secondary strucs. (dormers etc.) 1. Flat extension 2. _____
Windows (types, materials, etc.)
Awning, metal, single, paired, 4 stacked
Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, brick veneer paneling
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____		
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____			
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

W ELEV: single door w/ metal frame screen door, beneath a flat roof extension

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath a flat roof extension supported by metal porch supports w/ decorative scroll pattern

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building has a concrete block structural system clad in stucco and brick veneer with clapboard siding in the gable ends. An attached one-car carport with rear and side utility room is located on the south elevation.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
| <input checked="" type="checkbox"/> other methods (describe) <u>USDA historic aerial photographs (PALMM)</u> | | | |

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital **AND** hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14697**
Field Date 10-29-2019
Form Date 11-6-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 9925 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 9925 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Hervel Circle & Lanway Drive
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-ZZZ-000002-11120.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367150 Northing 3102331
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1962 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1962 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Robert D. Boughner & Robert D. Boughner, Jr. (2017); Robert & Anita Russ

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. Brick 3.
Roof Type(s) 1. Hip 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.
Windows (types, materials, etc.)
Awning, metal, single, paired, 2-stacked, 3-stacked; Picture, metal, single, central pane flanked by 3-stacked lights
Distinguishing Architectural Features (exterior or interior ornaments)
brick planter box, brick windowsills, overhanging eaves
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
c.1962 detached garage

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

W ELEV: single door w/ metal security bar door and sidelights, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath the principal roof with concrete block porch supports

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

The Masonry Vernacular style building has an open walkway with a brick planter box beneath the principal roof with concrete block porch supports. An attached two-car carport with rear utility room is located on the south elevation.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
| <input checked="" type="checkbox"/> other methods (describe) <u>USDA historic aerial photographs (PALMM)</u> | | | |

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14698**
Field Date 10-29-2019
Form Date 11-7-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 10001 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 10001 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Hervel Circle & Lanway Drive
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 7 / PG 58
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 18 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-18-28-20-25B-000000-00014.0 Landgrant _____
Subdivision Name North Tampa Land Co Sub Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367115 Northing 3102361
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1968 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1968 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, siding, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Nafees & Zeenat Ahmad (2018); Howard E. Ritchie

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Vinyl 2. _____ 3. _____
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____
Windows (types, materials, etc.)
SHS, vinyl, single, paired, 1/1; Picture, vinyl, single, one-light
Distinguishing Architectural Features (exterior or interior ornaments)
Wood trim around windows and doors, overhanging eaves
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____	
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Wood frame 2. 3.
Foundation Type(s): 1. Piers 2. Continuous
Foundation Material(s): 1. Obscured 2. Concrete Block

Main Entrance (stylistic details)

W ELEV: single door, beneath a gable roof supported by squared wooden porch supports

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: open, partial width, beneath a gable roof supported by squared wooden porch supports w/ wooden railing and accessed by steps w/ wooden railing.

Condition (overall resource condition): []excellent []good [x]fair []deteriorated []ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building that first appears on historic aerial photographs in 1968.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x]FMSF record search (sites/surveys) []library research []building permits []Sanborn maps
[]FL State Archives/photo collection []city directory []occupant/owner interview []plat maps
[x]property appraiser / tax records []newspaper files []neighbor interview []Public Lands Survey (DEP)
[]cultural resource survey (CRAS) []historic photos []interior inspection []HABS/HAER record search
[x]other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? []yes [x]no []insufficient information
Appears to meet the criteria for National Register listing as part of a district? []yes [x]no []insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments
1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE
When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 18





HISTORICAL STRUCTURE FORM
FLORIDA MASTER SITE FILE
Version 5.0 3/19

Site#8 HI14699
Field Date 10-29-2019
Form Date 11-7-2019
Recorder #

[X] Original
[] Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the Guide to Historical Structure Forms for detailed instructions.

Site Name(s) (address if none) 10003 Morris Bridge Road
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs
National Register Category (please check one) [X]building []structure []district []site []object
Ownership: []private-profit []private-nonprofit [X]private-individual []private-nonspecific []city []county []state []federal []Native American []foreign []unknown

LOCATION & MAPPING

Address: 10003 Morris Bridge Road
Cross Streets (nearest / between) Between Hervel Circle & Lanway Drive
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 7 / PG 58
City / Town (within 3 miles) Temple Terrace In City Limits? []yes []no [X]unknown County Hillsborough
Township 28S Range 20E Section 18 1/4 section: []NW []SW []SE []NE Irregular-name:
Tax Parcel # U-18-28-20-25B-000000-00013.2 Landgrant
Subdivision Name North Tampa Land Co Sub Block Lot
UTM Coordinates: Zone []16 [X]17 Easting 3671131 Northing 3102384
Other Coordinates: X: Y: Coordinate System & Datum
Name of Public Tract (e.g., park)

HISTORY

Construction Year: 1947 []approximately []year listed or earlier [X]year listed or later
Original Use Residence, private From (year): 1947 To (year): CURR
Current Use From (year): To (year):
Other Use From (year): To (year):
Moves: []yes [X]no []unknown Date: Original address:
Alterations: [X]yes []no []unknown Date: Nature Roofing, windows, trim
Additions: [X]yes []no []unknown Date: Nature W elev, E elev
Architect (last name first): Builder (last name first):
Ownership History (especially original owner, dates, profession, etc.)
Nafees & Zeenat Ahmad (2018); Kevin & Kathryn Smith (2010); Bonnie & Ronald Smith (1978); William Arnold, Sr.

Is the Resource Affected by a Local Preservation Ordinance? []yes []no [X]unknown Describe

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 2
Exterior Fabric(s) 1. Stucco 2. Wood/Plywood 3.
Roof Type(s) 1. Hip 2. 3.
Roof Material(s) 1. Other 2. 3. Metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. Gable extension 2. Shed extension

Windows (types, materials, etc.)
SHS, vinyl, single, paired, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, stone veneer shutters, artificial masonry veneer trim around windows

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic swimming pool

Table with 3 columns: DHR USE ONLY, OFFICIAL EVALUATION, DHR USE ONLY. Includes fields for NR List Date, SHPO listing criteria, and Owner Objection.

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Concrete, Generic 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details) W ELEV: single door w/ oval light, beneath a shed roof

Porch Descriptions (types, locations, roof types, etc.) W/ENTRANCE: open, partial width, beneath a shed roof extension w/ screening and a stone half wall

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource A two-story Masonry Vernacular style building w/ a large one-story addition on the W elevation consisting of two front gable extensions connected w/ a shed roof extension.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed) The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.) 1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1 2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites) 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors, Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community, 2017



USGS Thonotosassa
Township 28 South, Range 20 East, Section 18





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14700**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 10009 Morris Bridge Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 10009 Direction _____ Street Name Morris Bridge Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Between Hervel Circle & Lanway Drive
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 7 / PG 58
City / Town (within 3 miles) Temple Terrace In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 18 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-18-28-20-25B-000000-00013.3 Landgrant _____
Subdivision Name North Tampa Land Co Sub Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367107 Northing 3102412
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1968 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1968 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding
Additions: yes no unknown Date: _____ Nature Carport
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Freddie Taylor III (2018); MBBS Flip Fund (2017); Castle 2016 LLC (2016); T. Whitener (2001); B. Westberry (1997); G. Hardin (1984); P. Gatta (1971); Gilbert Hardin

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Frame Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Artif masonry veneer 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
Picture, vinyl, single, 1-light; SHS, vinyl, single, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Wood trim around windows, artificial masonry veneer along foundation, overhanging eaves w/ boxed rafter tails

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Wood frame 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

W ELEV: single door w/ arched light, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: incised, partial width, beneath the principal roof w/screening and an artificial masonry veneer half wall

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Frame Vernacular style building w/ artificial masonry veneer and an attached carport on the W elevation.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 18





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14701**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8917 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8917 Direction _____ Street Name Navajo Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Navajo Avenue & Morris Bridge Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 37 / PG 47
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-1IL-000000-00036.0 Landgrant _____
Subdivision Name Davis Terrace Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367055 Northing 3102673
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1964 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1964 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, partially enclosed carport
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Paulia & Richard White (2017); Central Tampa Investments, LLC (2016); Betty E. McDowell

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan L-shaped Number of Stories 1
Exterior Fabric(s) 1. Concrete block 2. Wood/Plywood 3. _____
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
SHS, metal, single, paired, 2/2

Distinguishing Architectural Features (exterior or interior ornaments)
Rusticated stucco windowsills, overhanging eaves w/ boxed rafter tails

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____		
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____			
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____
 Structural System(s): 1. Concrete block 2. _____ 3. _____
 Foundation Type(s): 1. Slab 2. _____
 Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

N ELEV: single door w/ fanlight, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

N/ENTRANCE: incised, partial width, beneath the principal roof supported by squared wooden porch supports.

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/plywood siding in the gable ends and an attached carport partially enclosed w/ plywood siding and a wooden lattice.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- FMSF record search (sites/surveys) library research building permits Sanborn maps
- FL State Archives/photo collection city directory occupant/owner interview plat maps
- property appraiser / tax records newspaper files neighbor interview Public Lands Survey (DEP)
- cultural resource survey (CRAS) historic photos interior inspection HABS/HAER record search
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

- Appears to meet the criteria for National Register listing individually? yes no insufficient information
 Appears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. _____ 3. _____ 5. _____
 2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
 Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
 Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
 Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
 (address / phone / fax / e-mail)

Required Attachments

- ① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
- ② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- ③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital **AND** hard copy format (plain paper grayscale acceptable).
 Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14702**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8915 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Address: 8915 Navajo Avenue
Street Number Direction Street Name Street Type Suffix Direction
Cross Streets (nearest / between) _____
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 37 / PG 47
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-11L-000000-00035.0 Landgrant _____
Subdivision Name Davis Terrace Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367038 Northing 3102676
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1964 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1964 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, quoins
Additions: yes no unknown Date: _____ Nature Chimney, S Elev.
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Marc Tramontana & Kristen Kilmer (2005); Marc Tramontana (2000); Gerald & Joann Buie

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Wood/Plywood 3.
Roof Type(s) 1. Cross-gabled 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.

Windows (types, materials, etc.)
SHS, vinyl, single, 1/1; Sliding, vinyl, single, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, Stucco trim around windows, stucco quoins, overhanging eaves with boxed rafter tails

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 1 Chimney Material(s): 1. Stucco 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

N ELEV: single door w/ full-light storm door, beneath a gable roof

Porch Descriptions (types, locations, roof types, etc.)

N/ENTRANCE: open, partial width, beneath a gable roof supported by squared wooden porch supports

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ plywood siding in gable ends, a one-car garage w/ segmental door, and a c. 1993 chimney w/n the principal roof.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
| <input checked="" type="checkbox"/> other methods (describe) <u>USDA historic aerial photographs (PALMM)</u> | | | |

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital **AND** hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14703**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8913 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8913 Direction _____ Street Name Navajo Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Navajo Avenue & Morris Bridge Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 37 / PG 47
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-11L-000000-00034.0 Landgrant _____
Subdivision Name Davis Terrace Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367015 Northing 3102678
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1962 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1962 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Connor Vega & Yesenia Arroyo (2017); Percy Bruce (1997); Cecilia Germosen (1991); Kim Curry (1986); Steven Beach

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Brick 2. Stucco 3.
Roof Type(s) 1. Hip 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.
Windows (types, materials, etc.)
SHS, vinyl, single, paired, 1/1
Distinguishing Architectural Features (exterior or interior ornaments)
Brick windowsills, overhanging boxed eaves
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

N ELEV: single door, beneath a hip roof

Porch Descriptions (types, locations, roof types, etc.)

N/ENTRANCE: open, partial width, beneath a hip roof supported by squared wooden porch supports

Condition (overall resource condition): []excellent []good []fair []deteriorated []ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ an attached one-car garage w/ segmental garage door on the north elevation.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? []yes [x]no []insufficient information
Appears to meet the criteria for National Register listing as part of a district? []yes [x]no []insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

- 1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14704**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8918 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8918 Direction _____ Street Name Navajo Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Navajo Avenue & Morris Bridge Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map _____
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-11L-000000-00001.0 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting Northing
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1963 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1963 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, quoins
Additions: yes no unknown Date: _____ Nature _____
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Kathy & Thuy Manh Vu (1992); Robert Z. Thompson (1992); Robert G. Thompson

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. _____ 3. _____
Roof Type(s) 1. Hip 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
Sliding, vinyl, single, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, stucco quoins, overhanging boxed eaves

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 1 Chimney Material(s): 1. Stucco 2.
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

S ELEV: single door w/ oval light and security bar screen door, beneath a hip roof

Porch Descriptions (types, locations, roof types, etc.)

S/ENTRANCE: open, partial width, beneath a hip roof supported by metal porch supports w/ decorative scroll pattern

Condition (overall resource condition): []excellent []good [x]fair []deteriorated []ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ a stucco chimney w/n principal roof and an attached one-car carport w/ rear utility room and decorative scroll pattern metal support/railing.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x]FMSF record search (sites/surveys) []library research []building permits []Sanborn maps
[]FL State Archives/photo collection []city directory []occupant/owner interview []plat maps
[x]property appraiser / tax records []newspaper files []neighbor interview []Public Lands Survey (DEP)
[]cultural resource survey (CRAS) []historic photos []interior inspection []HABS/HAER record search
[x]other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? []yes [x]no []insufficient information
Appears to meet the criteria for National Register listing as part of a district? []yes [x]no []insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14705**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8916 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8916 Direction _____ Street Name Navajo Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Navajo Avenue & Morris Bridge Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 37 / PG 47
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 ¼ section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-11L-000000-00002.0 Landgrant _____
Subdivision Name Davis Terrace Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367036 Northing 3102724
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1964 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1964 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing
Additions: yes no unknown Date: _____ Nature E Elev.
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Marilis & Angel Nazario (2017); Rita Corrieri (2008); Joseph & Sophia Corrieri (1969); Don & Juliet Watson

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Brick 3. Wood/Plywood
Roof Type(s) 1. Cross-gabled 2. _____ 3. _____
Roof Material(s) 1. Composition shingles 2. Sheet metal:3V crimp 3. _____
Roof secondary strucs. (dormers etc.) 1. Shed extension 2. _____

Windows (types, materials, etc.)
SHS, metal, single, paired, 2/2

Distinguishing Architectural Features (exterior or interior ornaments)
Stucco windowsills, overhanging eaves w/ boxed rafter tails, metal porch supports

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic utility shed and above-ground swimming pool

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. Concrete block 2. Slab 3. Foundation Type(s): 1. Slab 2. Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details) S ELEV: single door w/ 3/4-light storm door, beneath a gable roof

Porch Descriptions (types, locations, roof types, etc.) S/ENTRANCE: open, partial width, beneath a gable roof supported by metal porch supports w/ a decorative floral pattern

Condition (overall resource condition): [] excellent [] good [x] fair [] deteriorated [] ruinous

Narrative Description of Resource A one-story Masonry Vernacular style building w/ stucco window sills and boxed rafter tails.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps [] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps [x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP) [] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search [x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) Publication of Archival Library and Museum Materials (PALMM), accessible online at: http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed) The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.) 1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc Document description Files, photos, research, documents File or accession #'s P19150.1 2) Document type Maintaining organization Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net (address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites) 3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS






AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14706**
Field Date 10-29-2019
Form Date 11-8-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8914 Navajo Avenue Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8914 Direction _____ Street Name Navajo Street Type Avenue Suffix Direction _____
Address: _____
Cross Streets (nearest / between) Navajo Avenue & Morris Bridge Road
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 37 / PG 47
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 19E Section 13 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-13-28-19-1IL-000000-00003.0 Landgrant _____
Subdivision Name Davis Terrace Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367016 Northing 3102723
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1963 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1963 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature N elev; enclosed carport
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
TAH 2017 2 Borrower, LLC (2017); TAH 2015 1 Borrower, LLC (2015); SFRH Tampa Holding (2014); Ramon Castillo(1996); Ralph & Dallas McDowell

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Brick 2. Vinyl 3. Stucco
Roof Type(s) 1. Cross-gabled 2. 3.
Roof Material(s) 1. Composition shingles 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.

Windows (types, materials, etc.)
SHS, vinyl, single, paired, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Brick windowsills, overhanging eaves w/ boxed rafter tails, fluted vinyl columns

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic swimming pool and utility sheds

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date	_____	Init.	_____
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date	_____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

S ELEV: single door, beneath a gable roof supported by fluted vinyl column porch supports

Porch Descriptions (types, locations, roof types, etc.)

S/ENTRANCE: open, partial width, beneath a gable roof supported by fluted vinyl column porch supports

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building w/ vinyl siding in gable ends and an enclosed carport converted into a one car garage w/ plywood siding.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--|---|---|--|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital **AND** hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT



AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 19 East, Section 13





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **HI14872**
Field Date 11-7-2019
Form Date 12-9-2019
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 8913 Bowles Road Multiple Listing (DHR only) _____
Survey Project Name CRAS I-75 from S of US 301 to N Bruce B Downs Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 8913 Direction _____ Street Name Bowles Street Type Road Suffix Direction _____
Address: _____
Cross Streets (nearest / between) _____
USGS 7.5 Map Name THONOTOSASSA USGS Date 1974 Plat or Other Map PB 25 / PG 11
City / Town (within 3 miles) Tampa In City Limits? yes no unknown County Hillsborough
Township 28S Range 20E Section 19 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # U-19-28-20-25H-000000-00003.2 Landgrant _____
Subdivision Name Clewis Muck Farms Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 367750 Northing 3101353
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1963 approximately year listed or earlier year listed or later
Original Use Residence, private From (year): 1963 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows
Additions: yes no unknown Date: _____ Nature N & E ELEV
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Travis & Jamie Malloy (2013); DL Holdings LLC (2012); David Johnston (2010); Robert G. Slate, Sr. Living Trust

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Brick 2. Wood/Plywood 3. _____
Roof Type(s) 1. Gable 2. _____ 3. _____
Roof Material(s) 1. Other 2. _____ 3. Sheet metal: Ribbed
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____
Windows (types, materials, etc.)
SHS, vinyl, paired, 1/1; Awning, metal, paired, 3-stacked
Distinguishing Architectural Features (exterior or interior ornaments)
Overhanging eaves w/ boxed rafter tails, brick windowsill
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Non-historic quonset hut and detached carport

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO – Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info	Date _____	Init. _____		
<input type="checkbox"/> Owner Objection	KEEPER – Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no	Date _____			
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

W ELEV: single door, beneath the principal roof

Porch Descriptions (types, locations, roof types, etc.)

W/ENTRANCE: incised, partial width, beneath the principal roof

Condition (overall resource condition): []excellent []good [x]fair []deteriorated []ruinous

Narrative Description of Resource

A one-story Masonry Vernacular style building with an enclosed carport on the N ELEV clad in plywood siding.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x]FMSF record search (sites/surveys) []library research []building permits []Sanborn maps
[]FL State Archives/photo collection []city directory []occupant/owner interview []plat maps
[x]property appraiser / tax records []newspaper files []neighbor interview []Public Lands Survey (DEP)
[]cultural resource survey (CRAS) []historic photos []interior inspection []HABS/HAER record search
[x]other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? []yes [x]no []insufficient information
Appears to meet the criteria for National Register listing as part of a district? []yes [x]no []insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

- 1. 3. 5.
2. 4. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19150.1
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 /aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS



DRAFT




AERIAL MAP





USGS Thonotosassa
Township 28 South, Range 20 East, Section 19



DRAFT

APPENDIX C: Demolished Building Letter



Florida's First Choice in Cultural Resource Management

December 10, 2019

Mr. Vincent Birdsong
Supervisor, Florida Master Site File
Division of Historical Resources
500 South Bronough Street
Tallahassee, FL 32399-0250

RE: Historic Resource Status

Dear Mr. Birdsong:

This letter is to inform you that background research and a historic field survey conducted in October 2019 has discovered that the following historic resources are no longer extant:

FMSF No.	ADDRESS/SITE NAME	YEAR BUILT	STYLE	SHPO EVALUATION
8HI11464	9016 Copeland Road	c1957	Masonry Vernacular	Ineligible
8HI11471	10345 Fisher Road	c1935	Frame Vernacular	Ineligible
8HI06900	2408 Graves Road	c1939	Frame Vernacular	Ineligible

Sincerely,

A handwritten signature in black ink that reads "Kim Irby m. only". The signature is written in a cursive, somewhat informal style.

Kim Irby, LEED AP
Architectural Historian

DRAFT

APPENDIX D: Survey Log

Ent D (FMSF only) _____



Survey Log Sheet

Florida Master Site File
Version 5.0 3/19

Survey # (FMSF only) _____

Consult *Guide to the Survey Log Sheet* for detailed instructions.

Manuscript Information

Survey Project (name and project phase)

I-75 (SR 93A) Historic Resources Survey Update, I-75 (SR 93A) from S of US 301 to Bruce B Downs Blvd, Hillsborough County, Florida

Report Title (exactly as on title page)

Historic Resources Survey Update Technical Memorandum, I-75 (SR 93A) from South of US 301 to North Bruce B Downs Blvd, Hillsborough County, Florida , FL FPID No. 419235-3-22-01

Report Authors (as on title page)

1. Marion Almy 3. Kimberly Irby
2. _____ 4. _____

Publication Year 2019

Number of Pages in Report (do not include site forms) 45

Publication Information (Give series, number in series, publisher and city. For article or chapter, cite page numbers. Use the style of *American Antiquity*.)

ACI, Sarasota, 2019 P19150.1

Supervisors of Fieldwork (even if same as author) Names Marion Almy

Affiliation of Fieldworkers: Organization Archaeological Consultants Inc City Sarasota

Key Words/Phrases (Don't use county name, or common words like *archaeology, structure, survey, architecture, etc.*)

1. I-75 3. 10426 Tanner Rd 5. _____ 7. _____
2. Turner Residence 4. _____ 6. _____ 8. _____

Survey Sponsors (corporation, government unit, organization, or person funding fieldwork)

Name _____ Organization Florida Dept of Transportation - District 7

Address/Phone/E-mail 11201 North McKinley Drive Tampa, Florida 33612-6456

Recorder of Log Sheet Kimberly M. Irby Date Log Sheet Completed 11-5-2019

Is this survey or project a continuation of a previous project? No Yes: Previous survey #s (FMSF only)

Project Area Mapping

Counties (select every county in which field survey was done; attach additional sheet if necessary)

1. Hillsborough 3. _____ 5. _____
2. _____ 4. _____ 6. _____

USGS 1:24,000 Map Names/Year of Latest Revision (attach additional sheet if necessary)

1. Name BRANDON Year 1956 4. Name WESLEY CHAPEL Year 1973
2. Name THONOTOSASSA Year 1974 5. Name _____ Year _____
3. Name LUTZ Year 1974 6. Name _____ Year _____

Field Dates and Project Area Description

Fieldwork Dates: Start 10-29-2019 End 10-30-2019 Total Area Surveyed (fill in one) _____ hectares 564.00 acres

Number of Distinct Tracts or Areas Surveyed 1

If Corridor (fill in one for each) Width: _____ meters 300 feet Length: _____ kilometers 17.20 miles

Research and Field Methods

Types of Survey (select all that apply): archaeological architectural historical/archival underwater
 damage assessment monitoring report other(describe): _____

Scope/Intensity/Procedures

background research; field survey; HRSU report prepared

Preliminary Methods (select as many as apply to the project as a whole)

Florida Archives (Gray Building) library research- local public local property or tax records other historic maps LIDAR
 Florida Photo Archives (Gray Building) library-special collection newspaper files soils maps or data other remote sensing
 Site File property search Public Lands Survey (maps at DEP) literature search windshield survey
 Site File survey search local informant(s) Sanborn Insurance maps aerial photography
 other (describe): _____

Archaeological Methods (select as many as apply to the project as a whole)

Check here if NO archaeological methods were used.
 surface collection, controlled shovel test-other screen size block excavation (at least 2x2 m) metal detector
 surface collection, uncontrolled water screen soil resistivity other remote sensing
 shovel test-1/4" screen posthole tests magnetometer pedestrian survey
 shovel test-1/8" screen auger tests side scan sonar unknown
 shovel test 1/16" screen coring ground penetrating radar (GPR)
 shovel test-unscreened test excavation (at least 1x2 m) LIDAR
 other (describe): _____

Historical/Architectural Methods (select as many as apply to the project as a whole)

Check here if NO historical/architectural methods were used.
 building permits demolition permits neighbor interview subdivision maps
 commercial permits windshield survey occupant interview tax records
 interior documentation local property records occupation permits unknown
 other (describe): _____

Survey Results

Resource Significance Evaluated? Yes No

Count of Previously Recorded Resources 1 Count of Newly Recorded Resources 24

List Previously Recorded Site ID#s with Site File Forms Completed (attach additional pages if necessary)

HI08742


List Newly Recorded Site ID#s (attach additional pages if necessary)

HI14684 through HI14706; HI14872

Site Forms Used: Site File Paper Forms Site File PDF Forms

REQUIRED: Attach Map of Survey or Project Area Boundary

SHPO USE ONLY SHPO USE ONLY SHPO USE ONLY
Origin of Report: 872 Public Lands UW 1A32 # _____ Academic Contract Avocational
 Grant Project # _____ Compliance Review: CRAT # _____
Type of Document: Archaeological Survey Historical/Architectural Survey Marine Survey Cell Tower CRAS Monitoring Report
 Overview Excavation Report Multi-Site Excavation Report Structure Detailed Report Library, Hist. or Archival Doc
 Desktop Analysis MPS MRA TG Other: _____
Document Destination: Plottable Projects Plotability: _____



I-75 from South of US 301 to North of Bruce B Downs
 Townships 30-28 South, Range 20 East,
 and Townships 28-27 South, Range 19 East.
 USGS Brandon, Thonotosassa, Wesley Chapel, and Lutz. Hillsborough County.

HRSU Technical Memorandum
 I-75 from South of US 301 to North of Bruce B Downs,
 Hillsborough County, Florida,
 FPID No.: 419235-3